

1 Products affected

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type			
02	007	013	0000002297	4797.XXXX	Connectors	4797 snap-in types
02	007	013	0000002297	4797.XXXX.XX	Connectors	4797 snap-in types

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

2 Type of change

All 4797 snap-in types have smaller snappers on L/N side.

3 Detailed description of change



Old style without notch



New snapper style (with or without notch)

4 Reason of change

We made a type new version of 4797 with notch (V-lock). Therefore the snap-in versions had to be changed.

5 Released date

Release for series production

ww16/2011

6 Impact of change and recommended action

Form: smaller snappers on L/N side
Fit: N/A
Function: N/A
Production Site: Change of tool
Product label: N/A

7 Reference Documents / Attachments

Kind of document	Document number	Remarks

4797					0118.2065	
Creation date:	Created by:	Release date:	Released by:	Notification No.	Index	Page
04.02.2011 13:28:04	SHA	17.02.2011	SHA	22041	-	1 von 1