# **SAFETY DATA SHEET**

Flux-Off Water Soluble

CP0722 v3.3 RS 298-7937

RS REACh revision date 01/06/10

# 1. IDENTIFICATION OF THE SUBSTANCE/PREPARATION AND OF THE COMPANY/UNDERTAKING

Identification of the substance of	or preparation
Product name	: Flux-Off Water Soluble
Synonyms	: ES830BE
Product type	: Aerosol.
Use of the	: CLEANING PRODUCTS
substance/preparation	
Company/undertaking identification	ation
Manufacturer	: ITW Chemtronics 8125 Cobb Center Drive Kennesaw, GA 30152
Distributor	RS Components Ltd, Birchington Road, Corby, Northants, NN17 9RS. Tel: +44 (0) 1536 402888 (8am to 8pm) Email: technical.help@rs-components.com
Importer	: ITW Contamination Control Skejby Nordlandsvej 307 DK-8200 Aarhus N Denmark Tel +45 87 400 220 Fax +45 87 400 222 Email: info@itw-cc.com
e-mail address of person responsible for this SDS	: askchemtronics@chemtronics.com
Emergency telephone number (with hours of operation)	: Chemtrec - 1-800-424-9300 or collect 703-527-3887
2. HAZARDS IDENTIF	ICATION

The product is classified as dangerous according to Directive 1999/45/EC and its amendments.

Classification	: F; R11 Xi; R36 R67
Physical/chemical hazards	: Extremely flammable.
Human health hazards	: Irritating to eyes. Vapours may cause drowsiness and dizziness.

See section 11 for more detailed information on health effects and symptoms.

#### 3. COMPOSITION/INFORMATION ON INGREDIENTS

Substance/preparation : Preparation

Ingredient name	CAS number	%	EC number	Classificatio	n
propan-2-ol	67-63-0	60 - 80	200-661-7	F; R11 Xi; R36 R67	[1] [2]
butane propyl acetate	106-97-8 109-60-4	10 - 15 1 - 3	203-448-7 203-686-1	F+; R12 F; R11 Xi; R36 R66, R67	[2] [1] [2]
See section 16 for the full text of the R-phrases declared above					

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment and hence require reporting in this section.

[1] Substance classified with a health or environmental hazard

[2] Substance with a workplace exposure limit

Occupational exposure limits, if available, are listed in section 8.

#### 4. FIRST AID MEASURES

#### First-aid measures

Inhalation

: Move exposed person to fresh air. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. Keep person warm and at rest. If not breathing, if breathing is irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained personnel. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. Get medical attention. If unconscious, place in recovery position and get medical attention immediately. Maintain an open airway. Loosen tight clothing such as a collar, tie, belt or waistband.

Flux-Off Water Soluble	CP0722 v3.3 RS 298-7937
4. FIRST AID MEAS	URES
Ingestion	: Wash out mouth with water. Remove dentures if any. Move exposed person to fresh air. Keep person warm and at rest. If material has been swallowed and the exposed person is conscious, give small quantities of water to drink. Stop if the exposed person feels sick as vomiting may be dangerous. Do not induce vomiting unless directed to do so by medical personnel. If vomiting occurs, the head should be kept low so that vomit does not enter the lungs. Get medical attention if adverse health effects persist or are severe. Never give anything by mouth to an unconscious person. If unconscious, place in recovery position and get medical attention immediately. Maintain an open airway. Loosen tight clothing such as a collar, tie, belt or waistband.
Skin contact	: Flush contaminated skin with plenty of water. Remove contaminated clothing and shoes. Get medical attention if symptoms occur. Wash clothing before reuse. Clean shoes thoroughly before reuse.
Eye contact	<ul> <li>Immediately flush eyes with plenty of water, occasionally lifting the upper and lower eyelids. Check for and remove any contact lenses. Continue to rinse for at least 10 minutes. Get medical attention.</li> </ul>
Protection of first-aiders	: No action shall be taken involving any personal risk or without suitable training. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation.
Notes to physician	: No specific treatment. Treat symptomatically. Contact poison treatment specialist immediately if large quantities have been ingested or inhaled.
Γ	ailed information on health effects and symptoms.
5. FIRE-FIGHTING	<b>NEASURES</b>
Extinguishing media	
Suitable	: Use an extinguishing agent suitable for the surrounding fire.
Not suitable	: None known.
Special exposure hazards	: Flammable aerosol. In a fire or if heated, a pressure increase will occur and the container may burst, with the risk of a subsequent explosion. Gas may accumulate in low or confined areas or travel a considerable distance to a source of ignition and flash back, causing fire or explosion. Bursting aerosol containers may be propelled from a fire at high speed. Runoff to sewer may create fire or explosion hazard.
	Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training. Move containers from fire area if this can be done without risk. Use water spray to keep fire-exposed containers cool.
Hazardous thermal decomposition products	: Decomposition products may include the following materials: carbon dioxide carbon monoxide
Special protective equipment for fire-fighters	: Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.
6. ACCIDENTAL RE	LEASE MEASURES

	6.	ACCIDENTAL	RELEASE MEASURES	)
--	----	------------	------------------	---

•••••••		
Personal precautions	:	No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. In the case of aerosols being ruptured, care should be taken due to the rapid escape of the pressurised contents and propellant. If a large number of containers are ruptured, treat as a bulk material spillage according to the instructions in the clean-up section. Do not touch or walk through spilt material. Shut off all ignition sources. No flares, smoking or flames in hazard area. Avoid breathing vapour or mist. Provide adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Put on appropriate personal protective equipment (see section 8).
Environmental precautions	:	Avoid dispersal of spilt material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air).
Methods for cleaning up		
Small spill	:	Stop leak if without risk. Move containers from spill area. Dilute with water and mop up if water-soluble. Alternatively, or if water-insoluble, absorb with an inert dry material and place in an appropriate waste disposal container. Use spark-proof tools and explosion-proof equipment. Dispose of via a licensed waste disposal contractor.
Large spill	:	Stop leak if without risk. Move containers from spill area. Approach the release from upwind. Prevent entry into sewers, water courses, basements or confined areas. Wash spillages into an effluent treatment plant or proceed as follows. Contain and collect spillage with non-combustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth and place in container for disposal according to local regulations (see section 13). Use spark-proof tools and explosion-proof equipment. Dispose of via a licensed waste disposal contractor. Contaminated absorbent material may pose the same hazard as the spilt product. Note: see section 1 for emergency contact information and section 13 for waste disposal.

Flux-Off Water Soluble	CP0722 v3.3 RS 298-7937
7. HANDLING AN	D STORAGE
Handling	: Put on appropriate personal protective equipment (see section 8). Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Workers should wash hands and face before eating, drinking and smoking. Pressurised container: protect from sunlight and do not expose to temperature exceeding 50°C. Do not pierce or burn, even after use. Do not ingest. Avoid contact with eyes, skin and clothing. Avoid breathing gas. Avoid breathing vapour or mist. Use only with adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Store and use away from heat, sparks, open flame or any other ignition source. Use explosion-proof electrical (ventilating, lighting and material handling) equipment. Use non-sparking tools. Empty containers retain product residue and can be hazardous.
Storage	: Store in accordance with local regulations. Store in a segregated and approved area. Store away from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see section 10) and food and drink. Eliminate all ignition sources. Use appropriate containment to avoid environmental contamination.
Packaging materials	
Recommended	: Use original container.

## 8. EXPOSURE CONTROLS/PERSONAL PROTECTION

Ingredient name	Occupational exposure limits
propan-2-ol	EH40/2005 WELs (United Kingdom (UK), 8/2007). STEL: 1250 mg/m <sup>3</sup> 15 minute(s). STEL: 500 ppm 15 minute(s). TWA: 999 mg/m <sup>3</sup> 8 hour(s).
butane	TWA: 400 ppm 8 hour(s). EH40/2005 WELs (United Kingdom (UK), 8/2007). STEL: 1810 mg/m <sup>3</sup> 15 minute(s). STEL: 750 ppm 15 minute(s). TWA: 1450 mg/m <sup>3</sup> 8 hour(s).
propyl acetate	TWA: 600 ppm 8 hour(s). <b>EH40/2005 WELs (United Kingdom (UK), 8/2007).</b> STEL: 1060 mg/m <sup>3</sup> 15 minute(s). STEL: 250 ppm 15 minute(s). TWA: 849 mg/m <sup>3</sup> 8 hour(s). TWA: 200 ppm 8 hour(s).
Recommended monitoring procedures	: If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectiveness of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to European Standard EN 689 for methods for the assessment of exposure by inhalation to chemical agents and national guidance documents for methods for the determination of hazardous substances.
Exposure controls	
Occupational exposure controls	: Use only with adequate ventilation. If user operations generate dust, fumes, gas, vapour or mist, use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering controls also need to keep gas, vapour or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment.
Hygiene measures	: Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.
Respiratory protection	: Use a properly fitted, air-purifying or air-fed respirator complying with an approved standard if a risk assessment indicates this is necessary. Respirator selection must be based on known or anticipated exposure levels, the hazards of the product and the safe working limits of the selected respirator.
Hand protection	: Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary.
Eye protection	: Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists or dusts.
Skin protection	: Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.
Environmental exposure controls	: Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.

Flux-Off Water Soluble

# CP0722 v3.3 RS 298-7937

# 9. PHYSICAL AND CHEMICAL PROPERTIES

General information	
Appearance	
Physical state	: Liquid.
Colour	: Colourless.
Odour	: Alcohol-like.
Important health, safety and	environmental information
Boiling point	: 82°C (179.6°F)
Melting point	: May start to solidify at the following temperature: -88.9°C (-128°F) This is based on data for the following ingredient: propan-2-ol. Weighted average: -89.06°C (-128.3°F)
Flash point	: Closed cup: 12°C (53.6°F). (Tagliabue.)
Explosive properties	: Not considered to be a product presenting a risk of explosion.
Vapour pressure	: 4.4 kPa (33 mm Hg) (at 20°C)
Relative density	: 0.79 (Water = 1)
Vapour density	: >1 (Air = 1)
Evaporation rate (butyl acetate = 1)	: <1
Other information	
Auto-ignition temperature	: Lowest known value: 399°C (750.2°F) (propan-2-ol).
10. STABILITY AND	REACTIVITY
Stability	: The product is stable.
Conditions to avoid	: Avoid all possible sources of ignition (spark or flame).
Materials to avoid	: No specific data.
Hazardous decomposition products	: Under normal conditions of storage and use, hazardous decomposition products should not be produced.
11. TOXICOLOGICAL	. INFORMATION

Potential acute health effects					
Inhalation	1	Irritant			
Ingestion	1	No known significant effects	or critical hazard	S.	
Skin contact	:	No known significant effects	or critical hazard	S.	
Eye contact	:	Irritating to eyes.			
Acute toxicity					
Product/ingredient name		Result	Species	Dose	Exposure
propan-2-ol		LD50 Dermal	Rabbit	12800 mg/kg	-
		LD50	Rat	2735 mg/kg	-
		Intraperitoneal			
		LD50	Rat	1088 mg/kg	-
		Intravenous			
		LD50 Oral	Rat	5045 mg/kg	-
		LD50 Oral	Rat	5000 mg/kg	-
		TDLo	Rat	800 mg/kg	-
		Intraperitoneal			
		LC50 Inhalation	Rat	16000 ppm	8 hours
		Gas.			
Butane		LC50 Inhalation	Rat	658 g/m3	4 hours
		Vapour			
propyl acetate		LD50 Dermal	Rabbit	>20 mL/kg	-
		LD50 Oral	Rat	9370 mg/kg	-

#### Potential chronic health effects

Product name	List name	Name on list	Classification	Notes
butane	UK Occupational Exposure Limits EH40 - WEL	butane	Carc.	
Chronic effects	: No known significant	effects or critical hazar	ds.	
Carcinogenicity	: ClassifiedNone.			
Mutagenicity	: No known significant effects or critical hazards.			
Teratogenicity	: No known significant	effects or critical hazar	rds.	
Developmental effects	: No known significant	effects or critical hazar	rds.	
Fertility effects	: No known significant	effects or critical hazar	ds.	

Flux-Off Water Soluble	CP0722 v3.3 RS 298-7937
11. TOXICOLOGIC	
Inhalation	: Adverse symptoms may include the following: nausea or vomiting respiratory tract irritation coughing headache drowsiness/fatigue dizziness/vertigo
Ingestion	: No specific data.
Skin	: No specific data.
Eyes	: Adverse symptoms may include the following: irritation watering redness
Target organs	: Contains material which causes damage to the following organs: eye, lens or cornea. Contains material which may cause damage to the following organs: lungs, the nervous system, upper respiratory tract, skin, central nervous system (CNS).

## **12. ECOLOGICAL INFORMATION**

Environmental effects	: No known significant e	effects or critical hazards.					
Aquatic ecotoxicity Product/ingredient name propan-2-ol	Test -	Result Acute LC50 11130000 ug/L Fresh water	Species Fish - Fathead minnow - Pimephales promelas - Juvenile (Fledgling, Hatchling, Weanling) - 4 to 8 weeks - 1.1 to 3.1	Exposure 96 hours			
	-	Acute LC50 10400000 to 10600000 ug/L Fresh water	cm Fish - Fathead minnow - Pimephales promelas - 29 days - 20 mm - 0.103 g	96 hours			
	-	Acute LC50 9640000 to 10000000 ug/L Fresh water	Fish - Fathead minnow - Pimephales promelas - 31 days - 20.6 mm - 0.117 g	96 hours			
	-	Acute LC50 6550000 to 7450000 ug/L Fresh water	Fish - Fathead minnow - Pimephales promelas - 31 days - 17.4 mm - 0.082 g	96 hours			
	-	Acute LC50 4200000 ug/L Fresh water	Fish - Harlequinfish, red rasbora - Rasbora heteromorpha - 1 to 3 cm	96 hours			
	-	Acute LC50 1400000 to 1950000 ug/L Marine water	Crustaceans - Common shrimp, sand shrimp - Crangon crangon	48 hours			
	-	Acute LC50 >1400000 ug/L	Fish - Western mosquitofish - Gambusia affinis - 20 to 30 mm	96 hours			
propyl acetate	-	Acute LC50 60000 to 64000 ug/L Fresh water	Fish - Fathead minnow - Pimephales promelas - 30 days - 20.4 mm - 0.148 g	96 hours			
Conclusion/Summary	: Not available.						
<u>Biodegradability</u> Conclusion/Summary	: Not available.						
Other adverse effects	-						

#### Flux-Off Water Soluble CP0722 v3.3 RS 298-7937

#### **13. DISPOSAL CONSIDERATIONS**

Methods of disposal

: The generation of waste should be avoided or minimised wherever possible. Empty containers or liners may retain some product residues. This material and its container must be disposed of in a safe way. Dispose of surplus and non-recyclable products via a licensed waste disposal contractor. Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Do not puncture or incinerate container.

#### Hazardous waste

: The classification of the product may meet the criteria for a hazardous waste.

#### **14. TRANSPORT INFORMATION**

International transport regulations						
Regulatory information	UN number	Proper shipping name	Classes	PG*	Label	Additional information
ADR/RID Class	UN1950	Aerosol.Flammable	2	-		-
ADN/ADNR Class	UN1950	Aerosol. Flammable	2	-		-
IMDG Class	UN1950	Aerosol. Flammable	2.1	-		-
IATA Class	UN1950	Aerosol. Flammable	2.1	-		-

PG\* : Packing group

#### **15. REGULATORY INFORMATION**

#### EU regulations

Classification and labeling have been determined according to EU Directives 67/548/EEC and 1999/45/EC (including amendments) and take into account the intended product use.

Hazard symbol or symbols	Extremely flammable, Irritant
Risk phrases	: R12- Extremely flammable.
	R36- Irritating to eyes. R67- Vapours may cause drowsiness and dizziness.
Safety phrases	: S16- Keep away from sources of ignition - No smoking.S51- Use only in well-ventilated areas.S23- Do not breathe gas/fumes/vapour/sprayS2- Keep out of the reach of children.
Product use	: Classification and labeling have been determined according to EU Directives 67/548/EEC and 1999/45/EC (including amendments) and take into account the intended product use. Industrial applications
Europe inventory	: All components are listed or exempted.

## 16. OTHER INFORMATION

Full text of R-phrases referred to in sections 2 and 3 - United Kingdom (UK)	:	R12- Extremely flammable. R11- Highly flammable. R36- Irritating to eyes. R66- Repeated exposure may cause skin dryness or cracking. R67- Vapours may cause drowsiness and dizziness.	
Full text of classifications referred to in sections 2 and 3 - United Kingdom (UK)	:	F+ - Extremely flammable F - Highly flammable Xi - Irritant	
<u>History</u>			
Date of printing	:	10/19/2009.	
Date of issue/Date of revision	1	10/19/2009.	
Date of previous issue	:	No previous validation.	
Version	1	1	
Prepared by	:	Not available.	
Indicates information that has changed from previously issued version.			
Notice to reader			

### **16. OTHER INFORMATION**

To the best of our knowledge, the information contained herein is accurate. However, neither the above-named supplier, nor any of its subsidiaries, assumes any liability whatsoever for the accuracy or completeness of the information contained herein.

Final determination of suitability of any material is the sole responsibility of the user. All materials may present unknown hazards and should be used with caution. Although certain hazards are described herein, we cannot guarantee that these are the only hazards that exist.