
PRODUCT CHANGE NOTICE

**Data Sheet Specification
Change for Intersil Products
ISL55110* and ISL55111***

**Refer to:
PCN12067**

Date: August 13, 2012

August 13, 2012

To: Our Valued Intersil Customer

Subject: **Data Sheet Specification Change for Intersil Products ISL55110* and ISL55111***

This notice is to inform you that Intersil has changed the data sheet specification for the ISL55110* and ISL55111* products. The change to the Electrical Specifications table aligns the data sheet with the product characteristics and is necessary to maintain product manufacturability in support of customer delivery requirements. The updated data sheet is available on the Intersil web site at <http://www.intersil.com/data/fn/fn6228.pdf>.

Products affected:

| | | | |
|-----------------|-----------------|--------------------|------------------|
| ISL55110IRZ | ISL55110IVZ | ISL55111IRZ | ISL55111IRZR5343 |
| ISL55110IRZ-T | ISL55110IVZ-T | ISL55111IRZ-T | ISL55111IVZ |
| ISL55110IRZ-T7A | ISL55110IVZ-T7A | ISL55111IRZ-TR5343 | ISL55111IVZ-T |

The data sheet electrical specification limit change is as follows:

| Parameter | Symbol | Current Limit | | | New Limit | | | Units |
|----------------------------------|--------|---------------|-----|-----|-----------|-----|-----|-------|
| | | Min | Typ | Max | Min | Typ | Max | |
| Driver Supply Power-Down Current | IH_PDN | - | - | 1 | - | - | 2.5 | μA |

There have been no changes made to the die/silicon. There will be no change in external marking of the packaged parts. Parts affected by this change are identifiable via Intersil's internal traceability system.

Intersil will take all necessary actions to conform to agreed upon customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to receive product electrically screened to the revised data sheet beginning *ninety* days from the date of this notification or earlier with approval.

If you have concerns with this notice, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Regards,



Jon Brewster
Intersil Corporation

PCN12067

CC: J. Touvell J. McNamara M. Carmody A. Robinson R. Pitts