

WR REWORK SETS

WR 2000 ER Code No.: T0053380870

consists of (incl. safety rests):



Technical details
www.weller.de

1 WR 2 Power unit Code No.: T0053377699

2 channel repair station

- **WP 65** Code No.: T0052921599
 - 30% faster heat up & up to 50% longer tip lifetime

The new WP 65 soldering iron with automatic stand-by function and "Fast Response" and optimized sensor positioning allows lower solder temperatures combined with up to 50% higher tip lifetime. Allowing reduced operational costs and an increase in productivity.

3 DSX 120 Code No.: T0051319899

120W powered an amazingly fast de-soldering iron

Extremely fast heat up, only 35 sec for ready to use $(50^{\circ} - 350^{\circ}C)$, up to 3 times longer life time of desoldering tip

WR 3000M ER Code No.: T0053368870

consists of (incl. safety rests):



Technical details
www.weller.de

UR 3M Power unit Code No.: T0053366699

3 channel repair station

DSX 120 Code No.: T0051319899

120W powered an amazingly fast de-soldering iron

Extremely fast heat up, only 35 sec for ready to use $(50^{\circ} - 350^{\circ}C)$, up to 3 times longer life time of desoldering tip.

3 WP 120 Code No.: T0052919399

120 W soldering iron with fast heat up and high level temperature stability

120W soldering iron ideal for cramp space which still need an iron which won't fatigue during its work load.

4 HAP 200 Code No.: T0052711699

Hot air with safety first (highest security)

The unique hot wire adjustment of the HAP 200 prevents overheating of the heating element even at slow air flow that means more safety and a longer life time.

Weller Tools GmbH Carl-Benz-Straße 2 74354 Besigheim Germany

Phone: +49 (0) 7143 / 580-0 Fax.: +49 (0) 7143 / 580 10 Email: info@weller-tools.com Web: www.weller-tools.com