

12500 TI Boulevard, MS 8640, Dallas, Texas 75243

PCN# 20130121000 Datasheet update for TLV320AIC3206/TLV320AIC3256 Information Only

 Date:
 1/24/2013

 To:
 Newark PCN

Dear Customer:

This is an information-only announcement of a change to a device that is currently offered by Texas Instruments.

The changes discussed within this PCN are for your information only. Please see the attachment details for the planned implementation date.

This notification period is per TI's standard process. Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (<u>PCN_ww_admin_team@list.ti.com</u>).

Sincerely,

PCN Team SC Business Services Phone: +1(214) 480-6037 Fax: +1(214) 480-6659

20130121000 Attachment: 1

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE

TLV320AIC3256IRSBT

CUSTOMER PART NUMBER

null

Technical details of this Product Change follow on the next page(s).

PCN Number: 20130121000 PCN Date: 01/24/2013								
Title: TLV320AIC3206/TLV320AIC3256 Data Sheet								
Customer Conta	Customer Contact:PCN ManagerPhone:+1(214)480-6037Dept:Quality Services							
Change Type:								I
Assembly Site	2			nbly Proce				Assembly Materials
Design				ical Specif				Mechanical Specification
Test Site		ᆜᆜ		ng/Shippir		ng		Test Process
Wafer Bump S		ļЦ		Bump Ma				Wafer Bump Process
Wafer Fab Sit	е		water	Fab Mate				Wafer Fab Process
-	1			PCN	Details			
Description of C	hange:							
sequencing require	ements nge hist	•						pply connections and es may be reviewed at the
TEXAS INSTRUMENTS	;							TLV320AIC3206
www.ti.com						SLAS649	B-D	ECEMBER 2010-REVISED JANUARY 2013
				REVISION	HISTORY			
Changes from Revisi	on A (Dec	embe	r 2010) to	Revision B				Page
			1					
Corrected typos and spelling errors throughout data sheet								
Added WCSP package (YZF) Updated block diagram to include Vsys pin								
Updated block diagram to include vsys pin Updated ordering part numbers								
Added Vsys pin definition								
Updated diagram to include Vsys pin								
Updated power supply section to include Vsys								
TLV320AIC3256 SLOS630B - DECEMBER 201	0-REVISED) JANUA		REVISION	HISTORY			TEXAS INSTRUMENTS www.ti.com
Changes from Revisio	n A (Dece	ember						Page
	-							
Added WCSP package (YZF) Updated block diagram to include Vsys pin								
Updated ordering part numbers								
Added Vsys pin definition								
Updated diagram to include Vsys pin								
	Updated power supply section to include Vsys							

The datasheet number will be changing.

Device Family	Change From:	Change To:	
TLV320AIC3206	SLAS649A	SLAS649B	
TLV320AIC3256	SLOS630A	SLOS630B	

The updated datasheet(s) can be accessed by the following link(s): <u>http://www.ti.com/product/tlv320aic3206</u> <u>http://www.ti.com/product/tlv320aic3256</u>

Reason for Change:

To more accurately reflect device characteristics

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

Electrical specification performance changes as indicated above.

Changes to product identification resulting from this PCN:

None

	Affe	cted	:
			_

TLV320AIC3206IRSBR	TLV320AIC3206IYZFR	TLV320AIC3256IRSBR	TLV320AIC3256IYZFR
TLV320AIC3206IRSBT	TLV320AIC3206IYZFT	TLV320AIC3256IRSBT	TLV320AIC3256IYZFT

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com