

0CA08-3004



Interface cable set for EA 110 plus i for one or two i-CON (0IC1000A, 0IC1000AC, 0IC1000AXT) or i-CON 2 (0IC2000A, 0IC2000AC, 0IC2000AIT, 0IC2000AXT) soldering stations to connect with the EA110 plus i solder fume extraction (0CA08-002). For protection of the drive motor, the ERSA EA 110 plus i has an automatic cut off feature.