



PRODUCT BULLETIN

Generic Copy

ISSUE DATE: 01-Oct-2013
NOTIFICATION: 15866
TITLE: MCF5275 ERRATA UPDATE
EFFECTIVE DATE: 02-Oct-2013

DEVICE(S)

MPN
MCF5274CVM166
MCF5274CVM166J
MCF5274LCVM166
MCF5274LCVM166J
MCF5274LVF166
MCF5274LVM133
MCF5274LVM166
MCF5274LVM166J
MCF5274VM133
MCF5274VM166
MCF5274VM166J
MCF5275CVM166
MCF5275CVM166J
MCF5275LCVM166
MCF5275LCVM166J

AFFECTED CHANGE CATEGORIES

- ERRATA

DESCRIPTION OF CHANGE

The MCF5275 chip errata document has been updated to include additional errata that have been identified.

The following errata has been added to the MCF5275 chip errata documentation:

SECF220: CCR[PSTEN] bit not implemented

The errata document can be found on the web here:

<http://www.freescale.com/files/32bit/doc/errata/MCF5275DE.pdf>

REASON FOR CHANGE

The errata documentation for MCF5275 has been updated.

ANTICIPATED IMPACT OF PRODUCT CHANGE(FORM, FIT, FUNCTION, OR RELIABILITY)

No changes have been made to the current production device. The errata describe existing conditions identified on current production devices. There are potential hardware and/or software implications to customers.

NOTE:

THE CHANGE(S) SPECIFIED IN THIS NOTIFICATION WILL BE IMPLEMENTED ON THE EFFECTIVE DATE LISTED ABOVE. To request further data or inquire about the notification, please enter a [Service Request](#)

For sample inquiries - please go to www.freescale.com

QUAL DATA AVAILABILITY DATE: 03-Oct-2013

QUALIFICATION STATUS: COMPLETED

QUALIFICATION PLAN:

N/A

RELIABILITY DATA SUMMARY:

N/A

ELECTRICAL CHARACTERISTIC SUMMARY:

N/A

CHANGED PART IDENTIFICATION:

N/A

ATTACHMENT(S):

External attachment(s) FOR this notification can be viewed AT:

[15866_MCF5275DE.pdf](#)
