

Global Change Notification (GCN)

Product Family: Various cables 10643584

GCN Number

Series: Partial p n s of serious series August 06, 2014

Date Issued

Reason For Change: MOQ (Not SPQ)

Change Description: The purpose of this letter is to inform you that change of the MOQ will be implemented on part numbers list on the sheet. The MOQ of before change and after change please refer to below picture. This letter takes the place of notice customer the reason of change is current MOQ is too small for the standard part number and caused low production efficiency. The part numbers as below: 887667400 887418700 887505318 887505310 887505410 887328100 887328712 887329100 887683530 887685300 687850001 887329200 887283200 887505418 887328912 687830004 887685510 687830007 887689810 887689830 887685200 887418020 887683510 687830008 887689800 887683520 887689820 687850003 687850006 887689920 687830002 687830034 887689910 887683500 887419020 687850004 687850002 687670021 887685500 887419010

Material	Product Type	SPQ	Current MOQ	New MOQ
887667400	DVI	50	50	200
887418700	DVI	200	200	1000
887505318	O/M - SATA	200	200	1000
887505310	O/M - SATA	200	200	1000
887505410	O/M - SATA	200	200	1000
887328100	Mini-USB/USB	120	120	1080
887328712	Mini-USB/USB	120	120	1080
887329100	Mini-USB/USB	160	160	1600
887683530	O/M-HDMI	20	100	200
887685300	O/M - DMS59	50	50	200
687850001	Mini-DP	100	200	500
887329200	Mini-USB/USB	120	120	3000
887283200	Mini-USB/USB	200	200	3000
887505418	O/M - SATA	200	200	3000
887328912	Mini-USB/USB	120	120	3000
687830004	Std DP	6	60	300
887685510	O/M - DMS59	16	48	320
687830007	Std DP	20	100	500
887689810	O/M-HDMI	50	100	500

The MOQ Before change and after change

887689810	O/M-HDMI	50	100	500
887689830	O/M-HDMI	20	60	500
887685200	O/M - DMS59	50	50	500
887418020	DVI	10	200	500
887683510	O/M-HDMI	50	100	500
687830008	Std DP	20	100	500
887689800	O/M-HDMI	50	100	500
887683520	O/M-HDMI	50	200	500
887689820	O/M-HDMI	50	100	500
687850003	Mini-DP	50	200	500
687850006	Mini-DP	50	200	500
887689920	O/M-HDMI	50	100	500
687830002	Std DP	20	100	500
687830034	Std DP	20	200	500
887689910	O/M-HDMI	50	200	500
887683500	O/M-HDMI	50	200	500
887419020	DVI	10	10	500
687850004	Mini-DP	100	200	500
687850002	Mini-DP	50	200	500
687670021	O/M-HDMI	50	200	500
887685500	O/M - DMS59	16	48	800
887419010	DVI	15	15	300

The MOQ Before change and after change

Part Numbers Affected: Please refer to CustomerPartList.csv attached to e-mail message.

Reason For Short Notice Exception: Not Applicable

Assessment Of Change (How Product Will Be Qualified & Validated): Change MOQ,Do not impact package

Internal Molex Qualification Date (Planned Date Information Available): February 06, 2015

Sample Availability Date (Changed Part): February 06, 2015

Date of Implementation: February 06, 2015

Method of Identifying Change: Change MOQ,Do not impact package

Recommended Replacement Parts: N/A

Last Time Buy Date for Obsolete Parts

Last Time Ship Date for Obsolete Parts

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com