

DESIGN/PROCESS CHANGE NOTIFICATION

This is to inform you that a change is being made to the following products.

This is a minor change that has no impact on product quality, reliability, electrical or mechanical performance. Affected products will remain fully compliant to all published specifications. Notification is being made for informational purposes only and there is no approval required. Products incorporating this change may be shipped interchangeably with existing unchanged products.

Please contact your local Customer Quality Engineer if you have any questions regarding this notification. Alternatively, you may send an email request for information to PCNSupport@fairchildsemi.com.

Implementation of change:

Expected First Shipment Date for Changed Product : N/A

Expected First Date Code of Changed Product : N/A

Description of Change (From) :

The products listed below being qualified for fabrication on Fairchild's Salt Lake 8" line per PCN P1B2A.

Description of Change (To) :

The products listed below are removed from the list of products being qualified for fabrication on Fairchild's Salt Lake 8" line per PCN P1B2A. These products will continue to be sourced by Salt Lake's 6" fabrication line.

Reason for Change:

The purpose of this ION is to notify the customer of a change to Fairchild Semiconductor's sourcing strategy for the products identified below. These products were scheduled to be qualified and produced in the 8" wafer fab in Salt Lake City, Utah according to PCN P1B2A. Due to changes in our manufacturing strategy, Fairchild is no longer planning to produce the products listed below in the Salt Lake 8" line, even if they have already been qualified. These products will continue to be sourced by the Salt Lake 6" fabrication line. Sample requests for these products from the Salt Lake 8" line will also be cancelled. The other products identified in PCN P1B2A, not listed below, will be sourced interchangeably between both the 6" and 8" fabrication lines per the original PCN.

You will be contacted by your local Customer Quality Engineer if you have any outstanding sample or data requests that are impacted by this change. Your CQE can help you select other products to sample from PCN P1B2A if required.

Affected Product(s):

FDB035N10A	FDB110N15A	FDB8444
FDB8445	FDB8447L	FDB86135
FDB8860	FDB8870	FDB8880
FDB8896	FDC637BNZ	FDC655BN
FDC655BN_F123	FDC655BN_G	FDC855N
FDC8601	FDC8602	FDC86244
FDC8878	FDC8884	FDC8886
FDD0207	FDD050N03B	FDD8444
FDD8445	FDD8447L	FDD8451
FDD8451_GSN00010	FDD8453LZ	FDD86110
FDD86252	FDD8770	FDD8778
FDD8780	FDD8782	FDD8796
FDD8870	FDD8874	FDD8876
FDD8878	FDD8880	FDD8880_G
FDD8882	FDD8896	FDD8896_G
FDFS6N548	FDFS6N754	FDG1024NZ
FDG410NZ	FDG8850NZ	FDH055N15A
FDI045N10A_F102	FDMA0104	FDMA1024NZ
FDMA1028NZ	FDMA1028NZ_F021	FDMA2002NZ
FDMA3028N	FDMA410NZ	FDMA420NZ
FDMA430NZ	FDMA7630	FDMA7632
FDMA7670	FDMA7672	FDMA8884
FDMA905P	FDMA905P_F130	FDMB2307NZ
FDMC0202S	FDMC0223	FDMC0223S
FDMC0225	FDMC0310AS	FDMC2512SDC
FDMC2514SDC	FDMC7200	FDMC7200S
FDMC7570S	FDMC7572S	FDMC7582
FDMC7660	FDMC7660DC	FDMC7660S
FDMC7664	FDMC7672	FDMC7672S
FDMC7672S_F126	FDMC7672_F125	FDMC7678
FDMC7680	FDMC7692	FDMC7692S
FDMC7692S_F126	FDMC7692S_F127	FDMC7692_F126
FDMC7692_SN00203	FDMC7696	FDMC8015L
FDMC8026S	FDMC8030	FDMC8200
FDMC8200S	FDMC8554	FDMC8588
FDMC86106LZ	FDMC8622	FDMC86240
FDMC86244	FDMC8854	FDMC8878
FDMC8878_F126	FDMC8882	FDMC8884
FDMC8884_F126	FDME1024NZT	FDME905PT
FDMF6700	FDMF6705	FDMF6705B

Affected Product(s):

FDMF6705V	FDMF6706B	FDMF6706C
FDMF6707B	FDML7610AS	FDML7610S
FDMQ8403	FDMS0300S	FDMS0302S
FDMS0306AS	FDMS0306S	FDMS0308AS
FDMS0308CS	FDMS0308S_SN00174	FDMS0309AS
FDMS0310AS	FDMS0310S	FDMS0312AS
FDMS0312S	FDMS0312S_SN00177	FDMS0343S
FDMS0346	FDMS0347	FDMS0349
FDMS0352S	FDMS0355AS	FDMS0355S
FDMS2504SDC	FDMS2506SDC	FDMS2508SDC
FDMS2510SDC	FDMS3016DC	FDMS3600AS
FDMS3600S	FDMS3602AS	FDMS3602S
FDMS3604AS	FDMS3604S	FDMS3606AS
FDMS3606S	FDMS3610S	FDMS3615S
FDMS3616S	FDMS3620S	FDMS3622S
FDMS3624S	FDMS3626S	FDMS3660S
FDMS3664S	FDMS3668S	FDMS7556S
FDMS7558S	FDMS7560S	FDMS7570S
FDMS7572S	FDMS7578	FDMS7580
FDMS7600AS	FDMS7602S	FDMS7603S
FDMS7606	FDMS7608S	FDMS7620S
FDMS7621S	FDMS7650	FDMS7650DC
FDMS7656AS	FDMS7658AS	FDMS7658AS_SN00232
FDMS7660	FDMS7660AS	FDMS7670
FDMS7670AS	FDMS7672	FDMS7672AS
FDMS7676	FDMS7680	FDMS7681
FDMS7682	FDMS7692	FDMS7692A
FDMS7694	FDMS7694_SN00176	FDMS7698
FDMS7700S	FDMS8018	FDMS8020
FDMS8023S	FDMS8025AS	FDMS8025S
FDMS8025S_SN00206	FDMS8026S	FDMS8027S
FDMS8027S_SN00204	FDMS8558S	FDMS8560S
FDMS8570S	FDMS86103L	FDMS86104
FDMS86105	FDMS8622	FDMS86252
FDN359BN	FDN359BN_F095	FDN8601
FDN86246	FDP027N08B_F102	FDP036N10A
FDP045N10A_F102	FDP150N10A_F102	FDP8447L
FDP8860	FDP8870	FDP8874
FDP8874_SN00117	FDP8880	FDP8896
FDPF045N10A	FDPF770N15A	FDS8447

Affected Product(s):

FDS8449	FDS8449_G	FDS86106
FDS86140	FDS86141	FDS86242
FDS86252	FDS8813NZ	FDS8817NZ
FDS8817NZ_G	FDS8817NZ_SBSP001	FDS8840NZ
FDS8842NZ	FDS8870	FDS8870_G
FDS8876	FDS8876_F40	FDS8878
FDS8878_F123	FDS8878_G	FDS8880
FDS8880_G	FDS8880_SN00134	FDS8882
FDS8884	FDS8884_G	FDS8896
FDS8896_SBSW008	FDS89141	FDS89161
FDS89161LZ	FDS8949	FDS8978
FDS8978_F40	FDS8984	FDS8984_F123
FDS8984_F40	FDT86102LZ	FDT86106LZ
FDT86113LZ	FDT86244	FDT86246
FDT86256	FDZ192NZ	FDZ372NZ
PCF2512W	PCF8554W	PCF8896W
PCF8978W	PCFD8870W	