

1 Products affected

Product hierarchy no. *	Part no.	SBU	Type / Description	Customer part no.
SBU PG PGU Type				
02 007 060 0000002254	See list below	Strip Block	4754	

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected							
4754.3000	4754.3200	4754.3400	4754.4000	4754.4200	4754.4400	4754.5000	4754.5200
4754.5400	4754.6000	4754.6200	4754.6400	4754.7000	4754.7200	4754.7400	4754.8000
4754.8200	4754.8400						


2 Type of change

Modification of approval marks.
Slight modification on the lateral indentation.


3 Detailed description of change

New combined cURus approval mark instead of separates UR and CSA marks.
Slight modification on the lateral indentation.


Old marking




New marking



Old form



New form



4754 Strip Block					0118.2241	
creation date	created by	release date	released by	notification no.	revision	page
2014-09-15	hotzar	2015-02-17	hotzar	27061		1 of 2

4 Reason of change

Consolidation of North American approval marks with the combined cURus mark.
Slight modification on the lateral indentation because of optimization of the injection process.

5 Release date

The change will be rolled-out individually by all part numbers affected starting ww 12/2015 and last approx. 12 months.

6 Impact of change and recommended action

Form:	Yes	Slight modification on the lateral indentation.
Fit:	No	There are no dimensional changes.
Function:	No	No change on the specification.
Production Site:	No	There is no change of the production site.
Product Label:	Yes	CSA and UR marks replaced by cURus mark.

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Data Sheet 4754		

4754 Strip Block					0118.2241	
creation date	created by	release date	released by	notification no.	revision	page
2014-09-15	hotzar	2015-02-17	hotzar	27061	—	2 of 2