



PCN Tracking Number: PCN\_FT\_020

Issue Date: 2015-09-2

## Product Change Notification

<b>Product Part Number</b>	<b>FT4222HQ Hi-Speed Quad SPI/I2C device</b>	<b>Estimated implementation date</b>
<b>Description of Change</b>	<b>Update from Rev A to Rev B to fix some issues</b>	<b>Sep 2015</b>
<b>Reason for Change</b>	<b>Fix exist issues.</b>	
<b>Detailed Description</b>	<b>All issues listed below have been fixed: Issue A : Android OS supporting issues. Issue B : CPU usage and latency time issue Issue C : I<sup>2</sup>C combined message issue Issue D : Default pin status Issue E : More suspend setting support</b>	
<b>Impact to Data sheet</b>	<b>Add IO status section in the new (for rev B) datasheet. No impact for other functions.</b>	
<b>Benefit of Change</b>	<b>Issues fixed</b>	
<b>Markings to distinguish revised from:</b>	<b>Device date code will be changed to a "B" to indicate revision B</b>	
<b>Sample Availability</b>	<b>Sep 2015</b>	
<b>Risk Assessment , Fit Form and Function &amp; reliability</b>	<b>Fit: Dimension have not changed. Form: Visual appearance is unchanged except for markings for rev B. Function: Device function remains unchanged but the initial and suspend default pin status was changed</b>	
<b>PDF Download</b>	<b><a href="http://www.ftdichip.com/Support/Documents/ProductChangeNotifications/PCN_FT_020.pdf">http://www.ftdichip.com/Support/Documents/ProductChangeNotifications/PCN_FT_020.pdf</a></b>	
<b>Others:</b>	<b>For the details, please refer the Technical notes:  <a href="http://www.ftdichip.com/Support/Documents/TechnicalNotes/TN_161_FT4222H_Errata_Technical_Note.pdf">http://www.ftdichip.com/Support/Documents/TechnicalNotes/TN_161_FT4222H Errata Technical Note.pdf</a></b>	