

"All permanent EPA [ESD protected areas] shall have defined boundaries. No item or activity within an EPA shall cause significant damage to ESDS [ESD sensitive items]. An EPA may take many forms, including the following: a bench; a store; an area of work; a field work area; a work station and equipment (for example, a solder flow machine)." [EN 61340-5-1 clause 5.1.1 General]


Vermason

ESD Protected Areas (EPAs) need to be identified as such. This sign is designed to attract attention and deliver a clear message to personnel and visitors.

The sign is printed with text and ESD sensitivity symbol per EN 61340-5-1 and User guide CLC/TR 61340-5-2.

Properties:

- Made of PVC foam sheet
- Size: 300mm (width) x 150mm (height)
- Thickness: 3mm
- 2 holes for hanging
- Printed with Vermason logo
- Text in German





Unless otherwise noted, tolerance ±10% Specifications and procedures subject to change without notice.



VERMASON UNIT C. 4TH DIMENSION. FOURTH AVENUE, LETCHWORTH. HERTS, SG6 2TD UK PHONE: +44 (0) 1462-672005 E-MAIL: Service@Vermason.co.uk, INTERNET: Vermason.co.uk

Drawing Number VER-27090

DATE: December 2015

© 2015 VERMASON