

Product Family	DIN	10708006	
		GCN Number	
Series	121019,121023,121024,121031,121124,121129,121132,121133,121178,12120 1,121206	August 17, 2015	
		Date Issued	
Reason For Change	MOQ (Not SPQ)		
Change Description	This is to inform you Molex is changing the MOQ (minimum order quantity) for 3 of its DIN part numbers from 2600pcs to 3000pcs. The part numbers affected are: 1211320188, 1211320221, 1211320222		
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.		
Reason For Short Notice Exception			
Assessment Of Change (How Product Will Be Qualified & Validated)	Packaging report available upon request.		
Internal Molex Qualification Date (Planned Date Information Available)	October 20, 2015		
Sample Availability Date (Changed Part)	November 02, 2015		
Date of Implementation	February 18, 2016		
Method of Identifying Change	Label on a box		
Recommended Replacement Parts	N/A		
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com