



# Product Change Notification



Product Group: Vishay Dale/October 7, 2014/PCN-DI-209-2014 Rev 0

## IHLP-3232DZ-01, IHLP-3232DZ-A1, and IHLP-3232DZ-L1 design change

**DESCRIPTION OF CHANGE:** The data sheet specifications for the 4.7uH inductance value are changing to correct error in the specifications.

Heat Rated Current changing from 7.5A to 7.25A

Saturation Current changing from 18.7A to 15.0A

SRF changing from 19MHz to 20MHz

**CLASSIFICATION OF CHANGE:** Assembly Process/Structure

**REASON FOR CHANGE:** Data sheet correction

**EXPECTED INFLUENCE ON QUALITY/RELIABILITY/PERFORMANCE:** None.

**PRODUCT CATEGORY:** Inductors

**PART NUMBERS/SERIES/FAMILIES AFFECTED:** IHLP3232DZER4R7M01 IHLP3232DZER4R7MA1  
IHLP3232DZER4R7ML1

**VISHAY BRAND(s):** Vishay Dale

**TIME SCHEDULE:** October 7, 2014

**SAMPLE AVAILABILITY:** N/A

**PRODUCT IDENTIFICATION:** Date Code 1441

**QUALIFICATION DATA:** N/A

**ISSUED BY:** Doug Lillie, Product Marketing Manager

**For further information, please contact your regional Vishay office.**

**CONTACT INFORMATION:**

**The Americas**

Vishay Intertechnology, Inc  
1505 East Highway 50  
P. O. Box 180  
Yankton, South Dakota 57078  
Ph: 1 605-665-9301  
Fax: 1 605-665-1627  
doug.lillie@vishay.com

**Europe**

Vishay Electronic GmbH  
Dr.-Felix-Zandman-Platz 1  
95100 Selb  
Germany  
Ph: 49-9287-71-2282  
Fax: 49-9287-71-2496  
jens.walther@vishay.com

**Asia**

Vishay Asia Pte Ltd.  
25 Tampines Street 92  
Keppel Building #02-00  
Singapore 528877  
Ph: +65-788-6668  
Fax: +65-788-3383  
victor.goh@vishay.com