



PCN# : P545AAB
Issue Date : Apr. 16, 2015

Information Only Notification

This is to inform you that a change is being made to the following products.

This is a minor change that has no impact on product quality, reliability, electrical or mechanical performance. Affected products will remain fully compliant to all published specifications. Notification is being made for informational purposes only and there is no approval required. Products incorporating this change may be shipped interchangeably with existing unchanged products.

Please contact your local Customer Quality Engineer if you have any questions regarding this notification. Alternatively, you may send an email request for information to PCNSupport@fairchildsemi.com.

Implementation of change:

Expected First Shipment Date for Changed Product : Apr. 16, 2015

Expected First Date Code of Changed Product :1517

Description of Change (From) :
Datasheet Change Only to correct following errors

Page 4, Output Voltage Swing at 10kOhm to Vs/2;LO : min 0.1
Output Voltage Swing at 10kOhm to Vs/2;HI : max 2.6

Page 5, Output Voltage Swing at 10kOhm to Vs/2;LO : min 0.1
Output Voltage Swing at 10kOhm to Vs/2;HI : max 4.9

Description of Change (To) :

Page 4, Output Voltage Swing at 10kOhm to Vs/2;LO : min 0.1 -> max 0.1
Output Voltage Swing at 10kOhm to Vs/2;HI : max 2.6 -> min 2.6

Page 5, Output Voltage Swing at 10kOhm to Vs/2;LO : min 0.1 -> max 0.1
Output Voltage Swing at 10kOhm to Vs/2;HI : max 4.9 -> min 4.9

Reason for Change:

To correct datasheet error on pages 4 and 5, for Output Voltage Swing values

Á
ÁE^&c^áÁÚ[á ~ &G DÁÚ|^æ^Á^!Á; Á@Áá d^ Áe^&c^áÁ[á ~ &o/Á Á@Ááá^} á { Áææ@á/Á Á@ÁÚÔPÁ{ æÁ[~
!&Áá^ÁV@Á Áá Áæ^áÁ} Á; Á; æ • á Á Á[~ !Á[{] æ ^ q Á !| &^!{ ^} d Á d !^ È