Panasonic

Product Change Notice: Markings change on ECQU(L) and ECQU(G) series of XY capacitors in order to comply with new UL regulations.

PCN.PG25.05.02.2014 05.02.2014

About this Notice:

UL Standard 1414 and 1283 (Which regulated XY capacitors) expired on December 25th 2013. The new UL Standard 60384-14 is currently in effect. Panasonic has changed the markings on its ECQU(L) and ECQU(G) series of XY capacitors to reflect this change. Both series are fully compliant with the new UL regulations. The ECQU(A) series of X2 capacitors already complies with UL 60384-14 and therefore did not need a change in markings. **No change in raw materials or manufacturing process due to these UL changes.**

Effective Date:

Product produced by Panasonic on and after December 1st, 2013.

Change Details:

Marking

Please see before and after drawing below for the new markings.

	Current					Future				
ECQU(L)	Сар.	(a) SIDE	(b) SIDE	(c) SIDE		Сар.	(a) SIDE	(b) SIDE	(c) SIDE	
Series	102~682	M .001µF K	FU E C Q U L 275V~Y2/X2 250V~ 46/100/21 1 falle cade	G M F 1 3 2 4 0 0		102~682	M .001µF K	ECQUL 275V~Y2/X2 2017-10-10-10-10-10-10-10-10-10-10-10-10-10-		
	8 2 2~4 7 3	M .0082µF K	FU E C Q U L 275 V~ X 2 250 V~ 48/100/21 1 date cade	GMF 0 E MKT 1 3 2 4 0 0		8 2 2~2 2 5	M .0082µF K	E C Q U L 275 V~X2 △ Als □		
	5 6 3 ~ 1 0 5	M).056µF K 275V~	E C Q U L 46/100/21 0 G WF 150V- 12 0 S WKT					date cade		
	1 5 5 ~ 2 2 5	M 1. \$uF % 213V~	9) m E C Q U L 40/100/21 2007- 0 MRT 32 132400 date code			(t) (b)				
			April 1980 and 1980 a							
ECQU(G) Series	Сар.	(a) SIDE	(b) SIDE	(c) SIDE		Сар.	(a) SIDE	(b) SIDE	(c) SIDE	
	1 0 3 ~ 2 2 4	M . 01µF K	#U E C Q U G	≪ 17(W)		103~105	M . 01µF K	cRJa E C Q U G 300V~ ■11® X1 □ date code		
	274~105	M). 27µF K 300V∼	# E C Q U G # # 17 M			(a)				
							(t)	(b)		

Panasonic

Product Change Notice: Markings change on ECQU(L) and ECQU(G) series of XY capacitors in order to comply with new UL regulations.

PCN.PG25.05.02.2014 05.02.2014

	Influence on customer product - Product registered with the file number a) E79502 (UL1283): Need to change to new file number E62674 (UL UL60384) b) E62674 (UL1414): No change needed. c) E62674 (UL1283): No change needed, because file number is same as UL60384.
Affected Parts:	Please see attached excel spreadsheet
Datasheet(s):	See Attached. The new UL certificates for ECQU(L) and ECQU(G) series are included in the files supplementing this Product Change Notice.
Notes:	