



Expertise Applied | Answers Delivered

8755 W. Higgins Road  
Suite 500  
Chicago, IL 60631 [www.littelfuse.com](http://www.littelfuse.com)

October 28<sup>th</sup>, 2014

**Product Change Notification for Radial Varistor MPQ, MDQ and MOQ (PCN# 4080E)**

Dear Valued Customers,

Littelfuse would like to notify you of a change relating to the Minimum Packing Quantity (MPQ), Minimum Delivery Quantity (MDQ) and Minimum Order Quantity (MOQ) for radial varistors. There will be no changes to the electrical or dimensional specification.

This change will be effective from December 1<sup>st</sup>, 2014; during this transition period, customers are expected to receive the parts in two kinds of minimum packing quantity until existing inventory in Littelfuse warehouse and the distribution channels are consumed completely.

Affected Part Number Listing:



Affected Part  
Number Listing.xls



20141028 MPQ MDQ  
MOQ Change for Vari

Please respond to us by November 15<sup>th</sup>, 2014 to acknowledge notification of this change. If we do not hear from you then we will expect that this change has been accepted and no further action is required. Thank you.

Best Regards  
Johnny Chang  
Global Product Manager  
Littelfuse, Inc.  
Tel: +1 773 628 0603  
[www.littelfuse.com](http://www.littelfuse.com)