

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type				
02	006	016	0000001604	See list below	Power entry module with filter	5707	

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected				
5707.0101.113	5707.0201.313.01	5707.0401.313	5707.0601.313.01	5707.0801.113
5707.0101.313	5707.0203.313	5707.0401.313.01	5707.0603.313	5707.0801.313
5707.0103.313	5707.0203.313.21	5707.0403.313	5707.0603.313.01	5707.0801.313.01
5707.0103.313.21	5707.0205.313	5707.0403.313.21	5707.0603.313.21	5707.0801.313.21
5707.0105.313	5707.0205.313.01	5707.0405.313	5707.0605.313	5707.0803.313
5707.0201.113	5707.0401.113	5707.0601.113	5707.0613.313	5707.0803.313.21
5707.0201.313	5707.0401.113.21	5707.0601.313	5707.0613.313.21	5707.0805.313
5707.0103.413	5707.0403.413	5707.0403.413.01	5707.0603.413	5707.0803.413
5707.0203.413				
5707.0101.112	5707.0201.312	5707.0401.312	5707.0601.312	5707.0613.312.21
5707.0101.312	5707.0201.312.01	5707.0401.312.01	5707.0601.312.01	5707.0801.112
5707.0101.312.01	5707.0203.312	5707.0403.312	5707.0603.312	5707.0801.312
5707.0103.312	5707.0203.312.01	5707.0403.312.21	5707.0603.312.01	5707.0801.312.01
5707.0103.312.01	5707.0205.312	5707.0405.312	5707.0603.312.03	5707.0801.312.21
5707.0105.312	5707.0205.312.01	5707.0405.312.01	5707.0605.312	5707.0803.312
5707.0201.112	5707.0401.112	5707.0601.112	5707.0613.312	5707.0805.312
5707.0103.412	5707.0203.412.21	5707.0403.412.21	5707.0803.412	5707.0803.412.21
5707.0203.412	5707.0403.412	5707.0603.412		

2 Type of change

Filter cases have a new surface treatment process.

3 Detailed description of change

Surface treatment process of filter case has changed with no change of surface material.

Screw versions front-side



5707					0118.2277	
creation date	created by	release date	released by	notification no.	revision	page
2015-03-31	buechlp	2015-04-13	buechlp	26911	-	1 of 2

Screw versions rear-mounting



4 Reason of change

Improved production process.

5 Release date

The change will be rolled-out starting ww 16/2015 and lasts approx. 12 months depending on the variant.

6 Impact of change and recommended action

Form:	No	No change to form but more shiny surface
Fit:	No	There are no dimensional changes
Function:	No	This is a non-functional change
Production Site:	No	There is no change of the production site
Product Label:	No	No change to product label
Customer action:	No	Notification only

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
List of affected part numbers	-	5707_PCN_affected part numbers.xlsx
Data sheet	5707	http://www.schurter.com/pdf/english/typ_5707.pdf

5707					0118.2277	
creation date	created by	release date	released by	notification no.	revision	page
2015-03-31	buechlp	2015-04-13	buechlp	26911	-	2 of 2