

SCHURTER INC  
447 Aviation Boulevard  
Santa Rosa, CA 95403

TEL 707 636 3000  
FAX 707 636 3033  
www.schurter.com




## REINTRODUCTION & PRODUCT CHANGE NOTICE SCHURTER SPT 6.3X32mm Fuses

April 23, 2015

Newark Element 14  
217 Wilcox Ave  
Gaffney, SC 29341-0000

Please see the attached documents for important information regarding the reintroduction of the SCHURTER SPT 6.3X32mm series of fuses, which were discontinued in November of 2014. A product change notice accompanies the reintroduction. This notification is to inform you of the Product Change Notice (PCN) that was released for SCHURTER SPT 6.3X32 series fuses. **Please note that this PCN only applies to versions rated from 10A to 32A (inclusive).** Versions rated at 0.5A to 8A have not been changed.

As noted on the PCN, there is no change to Fit or Function. The improved version has ceramic tubing (See Figure 1), and the fuse element is now soldered internally to the fuse ferrules. The original version featured a glass tube and the fuse element was soldered externally. As previously mentioned, these changes only apply to versions rated at 10A and above. The changes were rolled out Week 6, Year 2015.



Here are links to the PCN and data sheet for the SPT 6.3X32mm series fuses as published on our website:

[PCN: SPT 6.3X32mm](#)

[Data Sheet: SPT 6.3X32mm](#)

Here is the complete list of part numbers that are included in the reintroduction (part numbers that are impacted by the PCN are noted in **bold text**):

Material Number	Description
0001.2521	SPT 6.3X32 FUSE 500mA T
0001.2522	SPT 6.3X32 FUSE 630mA T
0001.2523	SPT 6.3X32 FUSE 800mA T
0001.2524	SPT 6.3X32 FUSE 1A T
0001.2525	SPT 6.3X32 FUSE 1.25A T
0001.2526	SPT 6.3X32 FUSE 1.6A T
0001.2527	SPT 6.3X32 FUSE 2A T
0001.2528	SPT 6.3X32 FUSE 2.5A T
0001.2529	SPT 6.3X32 FUSE 3.15A T
0001.2530	SPT 6.3X32 FUSE 4A T
0001.2531	SPT 6.3X32 FUSE 5A T
0001.2532	SPT 6.3X32 FUSE 6.3A T
0001.2532.PT	SPT FUSE PT 3AG 6.3V
0001.2533	SPT 6.3X32 FUSE 8A T
<b>0001.2534</b>	<b>SPT 6.3X32 FUSE 10A T</b>
<b>0001.2535</b>	<b>SPT 6.3X32 FUSE 12.5A T</b>
<b>0001.2536</b>	<b>SPT 6.3X32 FUSE 16A T</b>
<b>0001.2537</b>	<b>SPT 6.3X32 FUSE 20A T</b>
<b>0001.2538</b>	<b>SPT 6.3X32 FUSE 25A T</b>
<b>0001.2539</b>	<b>SPT 6.3X32 FUSE 32A T</b>

Here is a list of customers who have purchased SCHURTER SPT 6.3X32mm series fuses from Newark Element 14 within the past two years:

Part Number	Customer	Mo/Yr	Quantity
0001.2524	DENTSPLY INTL INC	01/2013	400
0001.2524	DENTSPLY INTL INC	02/2013	200
0001.2524	DENTSPLY INTL INC	04/2013	200
0001.2524	DENTSPLY INTL INC	05/2013	400
0001.2524	DENTSPLY/RINN	05/2013	400
0001.2524	DENTSPLY/RINN	08/2013	400
0001.2524	DENTSPLY/RINN	09/2013	400
0001.2524	DENTSPLY/RINN	10/2013	400
0001.2524	DENTSPLY/RINN	11/2013	0
0001.2524	DENTSPLY/RINN	12/2013	400
0001.2524	DENTSPLY/RINN	01/2014	800

Part Number	Customer	Mo/Yr	Quantity
0001.2524	DENTSPLY/RINN	02/2014	400
0001.2524	DENTSPLY/RINN	04/2014	400
0001.2532	ATS INC	09/2014	10
<b>0001.2534</b>	<b>ELECTRIC SUPPLY INC</b>	<b>01/2014</b>	<b>10</b>
<b>0001.2535</b>	<b>WESTERN CONTAINER CORP</b>	<b>08/2014</b>	<b>20</b>

For any technical questions about these changes, please contact Nikila Kareesan at [nkareesan@schurterinc.com](mailto:nkareesan@schurterinc.com) or by phone at (707) 636-5497.

For quote or order inquiries, please contact your SCHURTER Inside Sales Representative.

For all other questions, please contact Clif Emmons at [commons@schurterinc.com](mailto:commons@schurterinc.com) or by phone at (707) 636-3004.