



Dear Valued Distributors,

Product Change Notice

A change has been made to the housing of most of our 6200N series fans.

Reason for change

Continuous product improvement

Description


Extended cable exit at the flange area

Lip at the strut / cable channel

Effect

Improved and easier assembly of the harness as well as improved position of the lead wire in the strut of the fan housing

Attachments

- PCN, 6200N Series Housing, Affected Parts.xlsx" 
 - Tab 1 is a listing of part numbers affected
 - Tab 2 is a listing of part numbers NOT affected

This is a running change, so the new and improved design will ship as stock of the current design depletes. Please note that depending on stock levels, you may receive a mixed shipment of both the current and new designs.

Please let me know if you have questions, or if you need any further information.

Thank you,

Jeannine