

12500 TI Boulevard, MS 8640, Dallas, Texas 75243

PCN# # 20140519002 TUSB2046BIVFR test site Information Only

Date: 5/21/2014 To: Newark/Farnell PCN

Dear Customer:

This is an information-only announcement of a change to a device that is currently offered by Texas Instruments.

The changes discussed within this PCN are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (<u>PCN ww admin team@list.ti.com</u>).

Sincerely,

PCN Team SC Business Services Phone: +1(214) 480-6037 Fax: +1(214) 480-6659

## 20140519002 Attachment: 1

## **Products Affected:**

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

## DEVICE

TUSB2046BIVFR

## **CUSTOMER PART NUMBER**

null

Technical details of this Product Change follow on the next page(s).

PCN Number:		20140519002					PCN Date:		05/21/2014	
Title: TUSB2046BIVFR Test site										
Customer Contact:		PCN Manager		Phone:	+1(214) 480-60	37	Dept:	Qua	Quality Services	
Change Type:										
Assembly Site				Design			Wafer Bump Site			
Assembly Process			Data Sheet			Wafer Bump Material				
Assembly Materials		S		Part number change			Wafer Bump Process			
Mechanical Specifica		cation	$\square$	Test Site			Wafer Fab Site			
Packing/Shipping/La		Labeling	Test Process			Wafer	Fab I	Materials		
						Wafer	Fab I	Process		
PCN Details										
Description of Change:										
Texas Instruments Incorporated is announcing an information only notification to move location of test for TUSB2046BIVFR from TI Taiwan to TI Philippines.										
Reason for Change:										
TI Philippines currently utilizes roadmap test solution.										
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):										
None										
Changes to product identification resulting from this PCN:										
None										
Product Affected:										
TUSB2046BIVFR										

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com