

12500 TI Boulevard, MS 8640, Dallas, Texas 75243

Notification# 20160406003 Datasheet for TPS3809J25-Q1/TPS3809L30-Q1/TPS3809K33-Q1/TPS3809I50-Q1 Information Only

Date: 4/8/2016

To: Newark/Farnell PCN

Dear Customer:

This is an information-only announcement of a change to a device that is currently offered by Texas Instruments.

The changes discussed within this notification are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (PCN www admin team@list.ti.com).

Sincerely,

PCN Team SC Business Services

20160406003 Information Only Attachments

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE

CUSTOMER PART NUMBER

null

TPS3809K33QDBVRQ1

Technical details of this Product Change follow on the next page(s).

PCN	Number:	20160406003			F	CN Da	ote: 04/08/2016	
Titl	e: Datasheet for	TPS3809J25-Q1/TPS3809L30-Q1/TPS3809K			9K3:	33-Q1/TPS3809I50-Q1		
Cus	stomer Contact:					Dept: Quality Services		
Change Type:								
	Assembly Site	Des	sign			Wafer	Bump Site	
Ħ	Assembly Process		ta Shee	t	Ħ		Bump Material	
				er change			Bump Process	
	Mechanical Specification Test S			Ĭ			Fab Site	
	Packing/Shipping/Labeling Test P			SS		Wafer	Fab Materials	
						Wafer	Fab Process	
Notification Details								
Description of Change:								
Texas Instruments Incorporated is announcing an information only notification.								
The product datasheet(s) is updated as seen in the change revision history below:								
TEXAS INSTRUMENTS								
TPS3809J25-Q1, TPS3809L30-Q1, TPS3809K33-Q1, TPS3809I50-Q1								
SGLS142B – JUNE 2008 – REVISED MARCH 2016 www.ti.com								
Cha	nges from Revision A (De	cember 2002) to Revision	n B				Page	
Added AEC-Q100 Qualified information in bullets								
Changed Applications list items								
Added ESD Ratings table, Feature Description section, Device Functional Modes, Application and Implementation								
5	section, Power Supply Recommendations section, Layout section, Device and Documentation Support section, and							
Mechanical, Packaging, and Orderable Information section								
Changed device part numbers by adding -Q1 to them throughout document								
Device Family Ch				je From:		Chang		
			SGLS:	L42A		SGLS	142B	
TPS3809K33-Q1/TPS3809I50-Q1								
These changes may be reviewed at the datasheet links provided.								
http://www.ti.com/product/tps3809i50-q1								
Reason for Change:								
To more accurately reflect device characteristics.								
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):								
No anticipated impact. This is a specification change announcement only. There are no changes								
to the actual device.								
Changes to product identification resulting from this PCN:								
None.								
Product Affected:								
	09I50QDBVRG4Q	2U3809K33QDBVRG	64Q1	TPS3809I50QDB			33809K33QDBVRQ1	
	09J25QDBVRG4Q	2U3809L30QDBVRG		TPS3809J25QDE			33809L30QDBVRQ1	
For questions regarding this notice, e-mails can be sent to the regional contacts shown below								
or your local Field Sales Representative.								
Location				E-Mail				
USA				PCNAmericasContact@list.ti.com				
Europe				PCNEuropeContact@list.ti.com				
Asia Pacific				PCNAsiaContact@list.ti.com				
Japan			PC	PCNJapanContact@list.ti.com				