



PROLINE G2




1




(2x)

2


P2FXXXX


(0x)


3

M12x25


4

M12


5


M12


"B" MM	QTY.
1200	12x
1300	12x
1400	12x
1500	12x
1600	16x
1700	16x
1800	16x
1900	16x
2000	20x
2100	20x
2200	20x
2300	20x
2400	24x
2500	24x
2600	24x
2700	24x
2800	28x
2900	28x
3000	28x

"B" MM	QTY.
1200	12x
1300	12x
1400	12x
1500	12x
1600	16x
1700	16x
1800	16x
1900	16x
2000	20x
2100	20x
2200	20x
2300	20x
2400	24x
2500	24x
2600	24x
2700	24x
2800	28x
2900	28x
3000	28x

"B" MM	QTY.
1200	12x
1300	12x
1400	12x
1500	12x
1600	16x
1700	16x
1800	16x
1900	16x
2000	20x
2100	20x
2200	20x
2300	20x
2400	24x
2500	24x
2600	24x
2700	24x
2800	28x
2900	28x
3000	28x

WARNING



Twisting or tipping cabinet set can cause serious injury or death, and product damage.

Minimize tipping by using recommended lifting bars that provide lifting points equidistance from ends of enclosure set.

CAUTION

Insecurely joined cabinets can come apart during lifting and can fall, causing bodily injury and product damage.

Ensure joining kit P2AJ or P2AJHF is properly installed between each enclosure to avoid product damage and bodily injury.

WARNING



Falling lifting bars can cause serious injury or death

When not in use, lay lifting bars flat.


NOTICE

If warning labels become illegible or damaged, replace them with new labels.

To apply new labels, completely remove the old label and clean the surface of all adhesive. Apply the new labels to a clean, dry surface.

To receive additional WARNING labels, call 1-800-355-3560.

WARNING



Loose fasteners can cause cabinet(s) to fall and cause serious injury or death and product damage.

Torque fasteners to 30 FT-LBS.

Use screws and washers in kits to attach lifting bars at each required lifting position of the cabinet(s) top to help avoid serious bodily injury or death due to loose fasteners.

