

Global Change Notification (GCN)

Product Family	SRC Conduit Interface	10695090
		GCN Number
Series	93286	June 17, 2015
		Date Issued
Reason For Change	Obsolescence	
Change Description	This is to inform you that Molex is obsoleting the 93286 female conduit interface due to quality issues caused by the tooling going end of life. We will be replacing it with the 93481 series. The 93481 tool will be capable of running both the male and female conduit interface.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	8D Corrective Action Changes	
Assessment Of Change (How Product Will Be Qualified & Validated)	This change has no effect on fit, form or function of this product. Report is available upon request.	
Internal Molex Qualification Date (Planned Date Information Available)	July 08, 2015	
Sample Availability Date (Changed Part)	July 09, 2015	
Date of Implementation	July 15, 2015	
Method of Identifying Change	New series number	
Recommended Replacement Parts	93481 series	
Last Time Buy Date for Obsolete Parts	June 26, 2015	
Last Time Ship Date for Obsolete Parts	June 30, 2015	

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com