

PCN: V16-002-48475413-0A

Product Change Notice

Issue Date: 9 Sept 2016**Change Type:**

Implementation of alternate InGaN Green die source for Chiplid part number listed below

Parts Affected:

HSMF-C114	HSMQ-C190	QSMF-C11B	QSMF-C16L	QSMQ-C151
HSMF-C115	HSMQ-C110	QSMF-C11F	QSMF-C16N	QSMQ-C186
HSMF-C118	HSMQ-C120	QSMF-C11H	QSMF-C16P	QSMQ-C195
HSMF-C125	HSMQ-C150	QSMF-C11J	QSMF-C16Q	QSMQ-C196
HSMF-C163	HSMQ-C170	QSMF-C11K	QSMF-C16R	QSMQ-C19B
HSMF-C176	HSMQ-C177	QSMF-C11Q	QSMM-C121	QSMQ-C19C
HSMF-C173	HSMQ-C190	QSMF-C11S	QSMM-C179	QSMQ-C19G
HSMQ-C110	HSMQ-C191	QSMF-C120	QSMM-C190-SS000	QSMQ-C19T
HSMQ-C120	HSMQ-C197	QSMF-C16F	QSMM-C190-ST000	QSMQ-C19U
HSMQ-C150	HSMQ-C265	QSMF-C16H	QSMQ-C111	QSMT-CG02
HSMQ-C170	HSMQ-C280	QSMF-C16J	QSMQ-C124	

Description and Extent of Change:

The selected die source met Broadcom qualification requirement

Reasons for Change:

To ensure assurance of supply

Effect of Change on Fit, Form, Function, Quality, or Reliability:

No change in fit, form and function as per datasheet

Effective Date of Change:

Shipment will contain new die starting 8 March 2017. No sorting is required.

Qualification Data:

Qualification data will be made available upon request.

These changes have been reviewed and approved by Broadcom Limited engineers and managers per Broadcom Limited procedure: Change Control and Customer Notification, 5962-6052-80.

Please contact your Broadcom Limited field sales for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.