

## Product Obsolescence Memo

TRIMPOT® TRIMMING POTENTIOMETERS



May, 2016

### **Bourns® Model TC33B 3 mm SMD Trimpot® Trimming Potentiometers to be Discontinued**

Bourns has decided to discontinue the [Model TC33B](#) 3 mm SMD Trimpot® Trimming Potentiometers. A lack of sales volume and diminishing demand necessitates this action. Regrettably, no replacement part numbers are available at this time.

Obsolete Part Numbers
TC33B-1-101E
TC33B-1-102E
TC33B-1-103E
TC33B-1-104E
TC33B-1-105E
TC33B-1-201E
TC33B-1-202E
TC33B-1-203E
TC33B-1-204E
TC33B-1-501E
TC33B-1-502E
TC33B-1-503E
TC33B-1-504E
TC33B-1-472E

Please plan for the following deadlines:

*Last time buy date: July 26, 2016*

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).