



# Product Change Notice

PCN Number: 15-1250-01  
Issue Date: 12-FEBRUARY-2016

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

<b>PRODUCTS AFFECTED:</b>	SP34063AEN-L/TR	SP6260AEK-L/TR	SP6260BEK-L/TR	SP6260CEK-L/TR
	SP6260EEK-L/TR	SP6260GEK-L/TR	SP6699EK-L/TR	SP78L05N-L/TR
	SPX431AM1-L/TR	SPX431AN-L/TR	XRP431LES5TRR3-F	XRP7618IGBTR-F
	XRP7659ISTR-F			

## CHANGE CATEGORY:

- |  |                                    |   |
|--|------------------------------------|---|
| <input checked="" type="checkbox"/> Material | <input type="checkbox"/> Process   | <input type="checkbox"/> Package          |
| <input type="checkbox"/> Design              | <input type="checkbox"/> Datasheet | <input type="checkbox"/> Packing/Shipping |
| <input type="checkbox"/> Other:              |                                    |   |

## DESCRIPTION OF CHANGE:

Qualification of copper wire bonding assembly in addition to currently qualified gold wire bonding assembly.

## IMPACT OF CHANGE:

There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 12-MAY-2016

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

### PROPRIETARY INFORMATION

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.