

Monday, June 27, 2016

PRODUCT CHANGE NOTIFICATION

No. KBE-0018

Kingbright Electronic Co. Ltd., Taiwan have advised that as a result of the discontinuation of bi-colour THT LEDs made with GaP chips and with common anode configuration a number of current Kingbright LEDs will be moved to End of Life (EOL) status. Alternatives for many items have been developed to take advantage of newer chip technology offering improved stability and luminous intensity.

This will affect only the part numbers detailed on the attached schedule. Please check which of the part numbers listed on the next page are purchased by your company and change to the listed replacement ASAP.

Data sheets for the replacement items and samples for approval are available upon request.

In summary, with affect from 1st October 2016 all listed part numbers will no longer be available.

Should you require any further information, please do not hesitate to contact us.

With best regards

ppa. Dipl. Ing. Michael Vogt*Technical Sales*Mailto: michael.vogt@kingbright-europe.de

Head office in Germany:

Lindenau 7 / Gewerbegebiet
D-47661 ISSUM
Tel. +49 (2835) 44 46-0
Fax +49 (2835) 44 46-29
info@kingbright-europe.de

Branch office in France:

33 rue Benoit Malon
F-92150 SURESNES
Tel. +33 01.71.12.61.28
Fax +33 01.71.12.61.36
info@kingbright-europe.fr

Monday, June 27, 2016

PRODUCT CHANGE NOTIFICATION

No. KBE-0018

Affected Part Numbers

L-115VEGW-CA
L-115WEGW-CA
L-115WEGW-CA-TNR2.54
L-115WEYW-CA
L-115WGYW-CA
L-115WLGYW-CA
L-3WEGW-CA
L-3WSRSGW-CA
L-489EGWT-CA
L-59EGW-CA
L-59EYW-CA
L-59GYW-CA
L-59SRSGC-CA
L-59SRSGW-CA
L-59SRSGW-CA-TNR2.54
L-5A9EGW-CA-12.3SF

Replacement

Please check replacement with us
L-115WSURKCGKW-CA
L-115WSURKCGKW-CA-TNR2.54
Please check replacement with us
Please check replacement with us
Please check replacement with us
L-3WSURKCGKW-CA
L-3WSURKCGKW-CA
Please check replacement with us
L-59SURKCGKW-CA
Please check replacement with us
Please check replacement with us
L-59SURKCGKC-CA
L-59SURKCGKW-CA
Please check replacement with us
Please check replacement with us

Head office in Germany:

Branch office in France: