



PCN# : P685AAB
Issue Date : Aug. 31, 2016

Information Only Notification

This is to inform you that a change is being made to the following products.

This is a minor change that has no impact on product quality, reliability, electrical or mechanical performance. Affected products will remain fully compliant to all published specifications. Notification is being made for informational purposes only and there is no approval required. Products incorporating this change may be shipped interchangeably with existing unchanged products on or after the issue date of this notification.

Please contact your local Customer Quality Engineer if you have any questions regarding this notification.

Implementation of change:

Description of Change (From) :

TO263 Carrier tape

Lead empty length: 72cm(45ea empty pockets, the innermost 2 blank layers of reel).

Tail empty pocket length: 80cm(50ea empty pockets).




Description of Change (To) :

TO263 Carrier tape

Lead empty length: 112cm(70ea empty pockets, the innermost 3 blank layers of reel).

Tail empty pocket length: 40cm(25ea empty pockets).



Reason for Change:

The change is to mitigate lead deformation during product transportation.

Affected Product(s):

FAN7093_F085	FCB070N65S3	FCB110N65F
FCB11N60TM	FCB20N60FTM	FCB20N60TM
FCB290N80	FCB36N60NTM	FDB0105N407L
FDB0165N807L	FDB016N04AL7	FDB024N04AL7
FDB024N06	FDB024N08BL7	FDB029N06
FDB031N08	FDB035AN06A0	FDB035AN06A0_SN00015
FDB035N10A	FDB045AN08A0	FDB045AN08A0_F085
FDB045AN08A0_SN00237	FDB047N10	FDB050AN06A0
FDB050AN06A0_SN00269	FDB060AN08A0	FDB0630N1507L
FDB070AN06A0	FDB075N15A	FDB075N15A_F065
FDB075N15A_TF065	FDB082N15A	FDB088N08
FDB088N08_F140	FDB088N08_F141	FDB110N15A
FDB120N10	FDB12N50FTM_WS	FDB12N50TM
FDB13AN06A0	FDB14N30TM	FDB150N10
FDB15N50	FDB16AN08A0	FDB20N50F
FDB2532	FDB2532_SN00238	FDB2552
FDB2552_SB82178	FDB2572	FDB2614
FDB2710	FDB28N30TM	FDB33N25TM
FDB3502	FDB3632	FDB3632_F101
FDB3632_SN00239	FDB3652	FDB3682
FDB38N30U	FDB390N15A	FDB44N25TM
FDB52N20TM	FDB7030BL	FDB8030L
FDB8444	FDB8445	FDB8447L
FDB86102LZ	FDB86135	FDB8832
FDB8860	FDB8870	FDB8880
FDB8896	FDBS09H04A_F085A	FFB10UP20STM
FFB20UP20DN_F085	FFB20UP20DN_SB82195	FFB20UP20DN_SB82216
FFB20UP20STM	FFB20UP30DNTM	FGB20N60SF
FGB20N60SFD	FGB20N60SFD_F085	FGB3040CS
FGB3040CS_SB82142	FGB3236_F085	FGB40N60SM
FGB5N60UNDF	FGB7N60UNDF	FGBS3040E1_SN00193
FJB102TM	FJB3307DTM	FJB5555TM
FQB10N50CFTM_WS	FQB11N40CTM	FQB11P06TM
FQB11P06TM_SP001	FQB11P06TM_TSP001	FQB12P20TM
FQB12P20TM_SB82075	FQB12P20TM_TSB82075	FQB19N20CTM
FQB19N20LTM	FQB19N20TM	FQB19N20TM_T
FQB1P50TM	FQB22P10TM	FQB22P10TM_F085
FQB22P10TM_T	FQB25N33TM_F085	FQB25N33TM_NB82122
FQB27P06TM	FQB30N06LTM	FQB33N10LTM
FQB33N10TM	FQB33N10TM_T	FQB34N20LTM

Affected Product(s):

FQB34N20TM_AM002	FQB34P10TM	FQB34P10TM_F085
FQB34P10TM_TF085	FQB44N10TM	FQB47P06TM_AM002
FQB4N80TM	FQB50N06LTM	FQB50N06TM
FQB55N10TM	FQB5N50CTM	FQB5N60CTM_WS
FQB5N90TM	FQB5N90TM_SN00260	FQB6N40CTM
FQB6N80TM	FQB7N60TM	FQB7N60TM_WS
FQB7P20TM	FQB7P20TM_F085	FQB8N60CTM
FQB8N60CTM_WS	FQB8N90CTM	FQB8P10TM
FQB9N50CTM	FQB9P25TM	HGT1S10N120BNS
HGT1S10N120BNST	HGT1S12N60A4DS	HGT1S20N60C3S9A
HUF75345S3ST	HUF75545S3ST	HUF75545S3ST_F101
HUF75545S3ST_SN00258	HUF75631S3ST	HUF75639S3ST
HUF75645S3ST	HUF75645S3ST_F101	HUF76429S3ST
HUF76439S3ST	HUF76639S3ST	HUFA75645S3S
IRFW630BTM_FP001	ISL9R1560S3ST	ISL9R18120S3ST
ISL9R860S3ST	ISL9V5045S3ST	KSB834WYTM
NDB5060L	NDB6020P	NDB6030PL
NDB6060L	RUR1S1560S9A	