

PRODUCT ADVISORY

Minimum Line Quantity Changes for Listed Intersil Products

**Refer to:
PA14064**

Date: December 19, 2014

December 19, 2014

To: Our Valued Intersil Customers

Subject: **Minimum Line Quantity Change**

This advisory is to inform you that Intersil has updated the minimum line quantity (MLQ) for the parts listed in this notice. This notice is distributed for information only as the change does not affect product form, fit or function.

A product list, citing the old and new MLQ (minimum order quantity) is included in this notice. These changes will be implemented on February 1, 2015.

These changes will affect all orders placed on the books on or after February 1, 2015 but will not affect any orders currently on the books or placed on the books prior to that date.

If you have concerns with this advisory, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Regards,



Jeffrey Touvell

Intersil Corporation

PA14064

CC: B. Everling R. Pitts R. Velliquette P. Graves

PA14064 Minimum Line Quantity

Marketing Part Number	Current MLQ (MOQ)	New MLQ (MOQ)	Marketing Part Number	Current MLQ (MOQ)	New MLQ (MOQ)
24502BVA	20	40	5962-8954801PA	96	192
29104BJA	10	30	5962-89620012A	56	112
5962-0620701Q3A	43	172	5962-8963501PA	144	192
5962-0620702Q3A	43	129	5962-89636012A	56	224
5962-0620703Q2A	112	168	5962-8963601GC	36	70
5962-0620704Q2A	112	168	5962-8963601PA	96	144
5962-0620705Q3A	43	172	5962-9051801MEA	75	200
5962-0620706Q3A	43	172	5962-9052501MQA	99	207
5962-0620707Q2A	112	224	5962-9052502MQA	36	72
5962-0620708Q2A	112	168	5962-9054302MQA	18	45
5962-0623501QPC	48	100	5962-9054901MQA	9	18
5962-0623502QPC	48	100	5962-9073101MEA	500	1000
5962-0623601QPC	48	100	5962-9088801MRA	57	171
5962-0623602QPC	48	100	5962-9204201MEA	175	500
5962-0625501QXC	30	100	5962-9204201MEAS2035	175	350
5962-8501601YA	39	78	5962-9467701M2A	56	112
5962-85016023A	37	43	77052012A	112	168
5962-8501602YA	39	65	7705202EA	75	200
5962-8512704XA	13	39	7705202EAS2035	75	175
5962-85131013A	23	66	7705202EAS2461	25	175
5962-8513101XA	39	78	7705302EA	300	900
5962-85131023A	22	43	7800302GC	40	100
5962-8513102XA	39	65	7800302PA	144	288
5962-8513103EA	75	150	78029013A	6	10
5962-85131073A	43	86	7802901JA	15	30
5962-8513107XA	78	156	8001601CA	50	75
5962-85131092A	112	168	81006122A	56	112
5962-8671601EA	125	300	8100617EA/MLB	75	125
5962-86860012A	56	168	81006222A	56	112
5962-8686001EA	50	100	8403602JA	30	60
5962-8687901EA	46	115	8403603JA	45	75
5962-8688001QA	18	45	8403606JA	30	60
5962-8757701RA	38	76	8405202QA	9	27
5962-8757702RA	38	76	84065013A	43	63
5962-8778301EA	125	300	8406501JA	45	105
5962-8778701CA	125	150	8406602QA	45	108
5962-8850201CA	75	175	8406602XA	30	60
5962-8869002JA	30	60	8406701RA	38	76
5962-8950201GC	57	100	8406801VA	40	100
5962-8954801GC	72	100	8406901RA	19	38

PA14064 Minimum Line Quantity

Marketing Part Number	Current MLQ (MOQ)	New MLQ (MOQ)	Marketing Part Number	Current MLQ (MOQ)	New MLQ (MOQ)
85015013A	20	43	HI1-0303/883R5507	150	500
8501501XA	26	52	HI1-0303-2	525	1500
CDP1802ACD3	36	63	HI1-0303R5254	1000	1500
DG411AK/883	500	1000	HI1-0390-2	150	400
HA1-2400/883	150	300	HI1-0506-2	143	299
HA1-2420-2	75	200	HI1-0506A-2	91	195
HA1-4900-2	100	200	HI1-0506A-8	65	130
HA1-4902/883	50	100	HI1-0507-2	286	572
HA1-4902-2	150	300	HI1-0508/883	250	500
HA1-5104/883	100	200	HI1-0508-2	500	1000
HA1-5104-2	175	450	HI1-0508A-8	125	225
HA1-5320-2	125	250	HI1-0509-2	250	600
HA2-2510/883	60	100	HI1-0509A-2	150	350
HA2-2520-2	100	200	HI1-0509A-8	125	250
HA2-2522-2	100	200	HI1-0546/883	52	114
HA2-2600-2	100	200	HI1-0546-2	143	286
HA2-2640-2	100	200	HI1-0547/883	52	104
HA2-2640-2ZR5254	100	200	HI1-0548/883	100	200
HA2-5002-2	100	200	HI1-0548-2	150	350
HA2-5002-2ZR5254	100	200	HI1-0549/883	100	200
HA2-5033-2	72	144	HI1-0549-2	175	400
HA2-5127/883	38	70	HI1-1818A-2	150	400
HA4-5002/883	112	168	HI1-5042-2	250	600
HA7-2510/883	144	288	HI1-5043-2	125	300
HA7-2520-2	240	576	HI1-5046A/883	100	200
HA7-2640-2	240	528	HI1-5051-2	125	300
HA7-5101/883	144	240	HI1-565ATD-2	45	60
HA7-5102-2	240	576	HI1-574ASD-2	52	78
HA7-5147-2	192	432	HI1-574ATD-2	26	52
HA7-5147R5254	192	384	HI1-674ATD/883	26	39
HD1-15530-8	15	30	HI4-0546/883	43	64
HD1-4702/883	100	200	HI4-0548/883	56	112
HD1-6402B/883	45	81	HI4-5051/883	56	112
HD1-6402R/883	99	198	HM1-6514/883	80	200
HD1-6409/883	57	114	HM1-6514B/883	60	120
HI1-0201/883	325	650	HM1-65162/883	45	75
HI1-0201-2	500	1500	HM1-65162C/883	45	135
HI1-0201HS/883	225	500	HM1-6551B/883	51	136
HI1-0201HS-2	200	500	HM1-65642/883	26	52
HI1-0303/883	150	500	HM1-65642B/883	26	39

PA14064 Minimum Line Quantity

Marketing Part Number	Current MLQ (MOQ)	New MLQ (MOQ)	Marketing Part Number	Current MLQ (MOQ)	New MLQ (MOQ)
HM1-6617/883	30	45	JM38510/12203BGA	30	60
HM1-6642B/883	30	90	JM38510/12204BGA	30	60
HS1-3182-8	92	161	JM38510/12205BGA	30	60
HS1-3182-9+	69	138	JM38510/12206BGA	30	60
HS1-3282-8	45	135	JM38510/19001BXA	52	117
HS4-3182-8	43	129	JM38510/19002BXA	39	78
ICL3221EMVZ	1920	4800	JM38510/19004BXA	26	52
ICL3221EMVZ-T	2500	5000	JM38510/19005BEA	50	75
ISL22316WMUEP	200	3000	JM38510/19006BEA	50	100
ISL22316WMUEP-TK	1000	3000	JM38510/19007BEA	100	250
ISL22326WMVEP	384	1536	JM38510/19008BEA	100	250
ISL22326WMVEP-TK	1000	2000	MD80C86-2/883	9	27
ISL22346WMVEP	296	814	MD80C86-2/B	18	27
ISL3178AEMBZ	980	1960	MD80C88/B	18	27
ISL3282EMRTEP-TK	1000	3000	MD80C88-2/883	9	18
ISL3298EMRTEP-TK	1000	3000	MD82C37A/B	18	45
ISL6406MVEP	384	2112	MD82C52/B	39	65
ISL6406MVEP-TK	1000	3000	MD82C54/B	45	105
ISL8560MREP	200	1000	MD82C55A/B	54	108
ISL9000AMRNCEP	400	3000	MD82C84A/B	60	100
ISL9000AMRNCEP-TK	1000	3000	MD82C88/B	38	57
ISLA112P25MREP	32	69	MD82C89/B	19	38
JM38510/12202BGA	20	50			