



## Product Change Notification (PCN)

PCN Number	501387	Date Issued	August 19, 2016
Product Family	Please refer to the full part list attachment for details.		
Series	Please refer to the full part list attachment for details.		
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change will affect the fit, form, function or appearance of the parts. Or, it may result in a change to the specification. The pictures below show an example of the possible differences.		
Reason for Short Notice	Corrective Actions		
Assessment of Change	No change to parts/components FFF		
Internal Molex Qualification Date	September 01, 2016		
Sample Availability Date (Changed Part)	September 01, 2016		
Planned Implementation Date	September 01, 2016		
Method of Identifying Change	Special marking on the product or packaging		

Before Change



After Change



*Move shell carrier link location from center to 2 sides to prevent potential burr caused by carrier link cutting/breakoff process.*



## Product Change Notification (PCN)

---

You may address any technical inquiries regarding this PCN by sending E-mail to [pcn\\_coordinator@molex.com](mailto:pcn_coordinator@molex.com) or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:501387**" in the e-mail Subject line for faster response.

RELEASED

**Molex, LLC**  
2222 Wellington Court  
Lisle, IL 60532  
TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)