

Global Change Notification (GCN)

Product Family	Modular Jack	10681354
		GCN Number
Series	85510, 85513, 85502, 85543, 85542, 95622, 93242	April 13, 2015
		Date Issued
Reason For Change	MOQ (Not SPQ)	
Change Description	This is to inform you that Molex is changing the MOQ on the parts listed below. The reason for this change is to eliminate the risk of damaged parts on the blister pack reel. Due to the height of the blister pack pocket there is a risk where the first winding of the blister pack steps up that the part at this point could get damaged. To prevent this we are increasing the number of empty pockets at the centre of the blister pack reel to ensure the empty pockets go beyond this step up.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	8D Corrective Action Changes	
Assessment Of Change (How Product Will Be Qualified & Validated)	This change has no affect on fit, form or function	
Internal Molex Qualification Date (Planned Date Information Available)		
Sample Availability Date (Changed Part)		
Date of Implementation	April 30, 2015	
Method of Identifying Change	Label on box with new quantity	
Recommended Replacement Parts		
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com