

User Registration

Register today to create your account on Silabs.com. Your personalized profile allows you to receive technical document updates, new product announcements, “how-to” and design documents, product change notices (PCN) and other valuable content available only to registered users. <http://www.silabs.com/profile>

Bulletin Date: 12/5/2014		Bulletin Effective Date: 12/5/2014	
Title: EZRadioPRO Si4x6x-B1B-FM and Si4438-B1C-FM errata			
Originator: Vivek Mohan		Phone: 1-408-702-1251	Dept: Marketing
Customer Contact: Kathy Haggar		Phone: (512) 532-5261	Dept: Sales
Bulletin Details			
Description: An errata document for Si4x6x-B1B-FM and Si4438-B1C-FM Sub GHz transceivers, transmitters and receivers has been issued and is available at www.silabs.com .			
Reason: Under certain conditions, Si4x6x-B1B-FM and Si4438-B1C-FM devices require workarounds for proper operation as described in the Si4x6x-B1B-FM Rev 1.2 data sheet, Si4438-B1C-FM Rev 1.0 data sheet and EZRadioPRO API documentation Rev 1.1.2. Please see Si4x6x-B1B-FM and Si4438-B1C-FM Errata for a detailed description, impact and work around for such issues.			
Product Identification: Si4464-B1B-FM Si4463-B1B-FM Si4461-B1B-FM Si4460-B1B-FM Si4362-B1B-FM Si4063-B1B-FM Si4060-B1B-FM Si4438-B1C-FM Si4464-B1B-FMR Si4463-B1B-FMR Si4461-B1B-FMR Si4460-B1B-FMR Si4362-B1B-FMR Si4063-B1B-FMR Si4060-B1B-FMR Si4438-B1C-FMR			
Note: The part numbers above include tape and reel variants which are denoted with an “R” at the end of the orderable part number.			
This change is considered a minor change which does not affect form, fit, function, quality, or reliability. The information is being provided as a customer courtesy.			
Please contact your local Silicon Labs sales representative with any questions about this notification. A list of Silicon Labs sales representatives may be found at www.silabs.com			
Customer Actions Needed: Review the errata document and take corrective action if applicable.			