

Global Change Notification (GCN)

Product Family	DMS	10704691
		GCN Number
Series	Partial PNs of 68773/68788/68768	July 24, 2015
		Date Issued
Reason For Change	Product Component Change	
Change Description	<p>This letter is to inform you that Molex will use Molex DMS conenctor 751351000 to replace 751351009 for below finished cable assemblies. The reason is that 751351009 will be obsoleted on Oct 26, 2015 at Molex, part number 751351000 can be used in place of 751351009 per Molex GCM#10679538. The plating of Shield component on replacement part is Bright Tin. Both conenctors are the same form, fit and function. cable assemblies PNs as below: 687730001 687730005 687730030 687730035 687730036 687880072 687880119 887685200 887685300 887685400 887685500 887685510</p>	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	Not Applicable	
Assessment Of Change (How Product Will Be Qualified & Validated)	No need any speacial qualification for the change,the only difference is the platting on front shield	
Internal Molex Qualification Date (Planned Date Information Available)	July 07, 2015	
Sample Availability Date (Changed Part)	January 30, 2016	
Date of Implementation	January 30, 2016	
Method of Identifying Change	Different connector PN in SAP	
Recommended Replacement Parts	N/A	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com