

**1 Products affected**

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type				
01	001	025	0000000205	See list below	Circuit Protection	USF 1206	n/a


\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected				
3413.0114.11	3413.0114.22	3413.0114.24	3413.0114.26	

**2 Type of change**

- Improved marking readability
- Change of body material

**3 Detailed description of change**



Letters do not change

**4 Reason of change**

- Symmetric marking to provide marking readability independent from device placement in blister.
- Necessary change of body material due to material phase out.

Product Change Notification					PCN_USF 1206 0.750 A		
owner	creation date	release date	released by	change order no	rev	page	D10-006-945
ganderka	2016-07-26	2016-08-09	bergerra	2010595	A	1 of 2	

**5 Release date**

The change takes effect in ww 32/16 (Date code 1632 or higher on label).

**6 Impact of change and recommended action**

Form	Yes	New body material and marking adjusted
Fit	No	There are no dimensional changes.
Function	No	This is a non-functional change
Production Site	No	There is no change of the production site.
Product Label	No	No label change
Customer Action	No	Notification only

**7 Reference Documents / Attachments**

Kind of document	Document number	Remarks
Data sheet	USF 1206	

Product Change Notification					PCN_USF 1206 0.750 A	
owner	creation date	release date	released by	change order no	rev	page
ganderka	2016-07-26	2016-08-09	bergerra	2010595	A	2 of 2
						D10-006-945