



Eaton
Electronics Division
5735 W. Las Positas Blvd #100
Pleasanton, CA 94588
www.eaton.com/electronics

Product Change Notice

PCN#: EE-PCN16043

11/21/2016

CLASSIFICATION OF CHANGE:

Documentation

DESCRIPTION OF CHANGE:

Maximum surge voltage is specified incorrectly on the datasheet. Change from 3.0V to 2.8V.

REASON FOR CHANGE:

Correct documentation

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices.

PARTS NUMBERS AFFECTED:

HB0820-2R5305-R	HB1840-2R5606-R
HB1020-2R5505-R	HB1860-2R5117-R
HB1030-2R5106-R	
HB1325-2R5156-R	
HB1625-2R5256-R	
HB1635-2R5356-R	

TIME SCHEDULE:

Start Shipment Date: N/A

Last Time Buy Date: N/A

Last Time Shipment Date: N/A

SAMPLE AVAILABILITY: N/A

QUALIFICATION DATA: N/A

ISSUED BY:

Global Product Manager: Jason Lee

CONTACT INFORMATION:

For questions or comments, please contact your local [Eaton sales representative](#).