

## PRODUCT CHANGE NOTIFICATION

Reactions to this notification are to be addressed to Mallory Sonalert Sales Representative or Quality Control

### PRODUCT / MODEL CHANGE

AST1240MLQ & AST1240MLTRQ

### CHANGE DESCRIPTION

Sound hole is located on opposite side of part as compared to how it was previously packaged and reeled

### REASON FOR CHANGE

New marking & reel assembly site

### CHANGE OF FIT / FORM / FUNCTION?

N/A – No change to the operation of parts.

### DISPOSITION OF OLD PRODUCT

Acceptable to use up current stock as is.

### ESTIMATED CODE DATE OF EFFECTED PRODUCT

1603-1 (Jan 18, 2016)

### COMMENTS:

NONE

  
Approved By: Dan Clark

TITLE: Quality Manager

DATE: January 18, 2017

By:

TITLE:

DATE: