



Process/Product Change Notification (PCN)

To be completed by PCN Coordinator					
PCN #	17-0035	Linear Driver Amp End of Life Notification	PCN Date	Mar 6, 2017	
Qorvo Information					
Initiator	David Rahn		Date	Mar 3, 2017	
Post to PCN Alert?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	E-mail	PCNresponse@qorvo.com	
PCN Information					
<input type="checkbox"/> Customer Approval Required		<input checked="" type="checkbox"/> Notification Only			
Type of Change:	<input type="checkbox"/> Major	<input type="checkbox"/> Minor	<input checked="" type="checkbox"/> Obsolescence		
Change Affects	<input type="checkbox"/> Form	<input type="checkbox"/> Fit	<input type="checkbox"/> Function	<input type="checkbox"/> Reliability	<input checked="" type="checkbox"/> N/A
The following applies to all change classifications (Major, Minor, Obsolescence)					
Description of Change:	EOL notification of 3 linear driver amps				
Reason for Change:	Planned process obsolescence				
Affected Products:	RFPA2089, RFPA2126, RFPA2189, RFPA3805, RFPA3807, RFPA3809, RFVA1027, RVA1007L, RVA2007L, RVA3007L				
The following only applies to Major and Minor Changes					
Affected Product Specification (if applicable):					
Detail of potential impact to customer:	Last time buy orders will need to be placed based on future demand				
Qualification Plan or Data (if applicable):					
Customer Samples Available (if applicable):					
Qualification Results Available (if applicable):					
Planned Implementation Date:					
Identification of Changed Product (if applicable):					
Comments and/or Supporting Data:					
The following only applies to Obsolescence Notifications					
Last Time Buy Date	Mar 10, 2018 --				
Last Time Ship Date	Mar 10, 2019 --				
Alternate Part Recommendation	TQP7M9101 is recommended replacement for RFPA2089 TQP7M9102 is recommended replacement for RFPA2189 TQP9111 is recommended replacement for RFPA3805 TQP7M9101 is recommended replacement for RFPA3807 TQP7M9103 is recommended replacement for RFPA3809 TQP7M9104 is recommended replacement for RFPA2126 RFVA1027, RVA1007L, RVA2007L and RVA3007L have no replacements				
Customer Acknowledgement/Responses	All Customer responses must be sent via e-mail to PCNResponse@qorvo.com . When replying, please include the PCN number in subject line. Lack of acknowledgement of the PCN within 30 days constitutes acceptance of the change. After acknowledgement, lack of additional response prior to the planned implementation date constitutes acceptance of the change. An acceptance, concern, sample order request or a request for further information should be submitted to Qorvo in a timely fashion, (i.e., customer should not wait to the end of the review period before responding). If the customer requires additional time to perform sample testing, beyond the stated planned implementation date, an extension must be negotiated with Qorvo. Any contractual PCN agreements made with Qorvo supersede these requirements.				
Qorvo 7628 Thorndike Road Greensboro, NC 27409-9421 Customer Service Phone: 336.678.5570					

QORVO Process Change Notification (PCN) Form

E-mail (PCN Related Correspondence Only): PCNResponse@qorvo.com
<http://www.qorvo.com>