

# Product Discontinuation



## EOL595

|                       |            |
|-----------------------|------------|
| ■ Last Order Date:    | 2017-12-31 |
| ■ Last Delivery Date: | 2018-6-30  |

Reason: Subcontractor assembly site no longer available

| DISCONTINUED   |               |                |         | NEW (REPLACEMENT) |                |                |                |
|----------------|---------------|----------------|---------|-------------------|----------------|----------------|----------------|
| Device         | Ordering Code | OPN            | Package | Device            | Ordering Code  | OPN            | Package        |
| IRAMS10UP60C-2 | SP001533460   | IRAMS10UP60C-2 | SIP 1   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMX16UP60A   | SP001533470   | IRAMX16UP60A   | SIP2    | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMS10UP60B-W | SP001533480   | IRAMS10UP60B-W | SIP 1   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAM136-0461G  | SP001533524   | IRAM136-0461G  | SIP 1   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMX30TP60A-2 | SP001535430   | IRAMX30TP60A-2 | SIP2    | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMS06UP60A-2 | SP001535440   | IRAMS06UP60A-2 | SIP 1   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMX16UP60B   | SP001535552   | IRAMX16UP60B   | SIP2    | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMS06UP60B   | SP001536848   | IRAMS06UP60B   | SIP 1   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAM136-1561A  | SP001536876   | IRAM136-1561A  | SIP1A   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMS12UP60A-2 | SP001536980   | IRAMS12UP60A-2 | SIP 1   | No Replacement    | No Replacement | No Replacement | No Replacement |

**Disclaimer:** The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

# Product Discontinuation



## EOL595

|                       |            |
|-----------------------|------------|
| ■ Last Order Date:    | 2017-12-31 |
| ■ Last Delivery Date: | 2018-6-30  |

| DISCONTINUED   |               |                |         | NEW (REPLACEMENT) |                |                |                |
|----------------|---------------|----------------|---------|-------------------|----------------|----------------|----------------|
| Device         | Ordering Code | OPN            | Package | Device            | Ordering Code  | OPN            | Package        |
| IRAMY20UP60B   | SP001537082   | IRAMY20UP60B   | SIP3    | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMS10UP60B-3 | SP001537092   | IRAMS10UP60B-3 | SIP 1   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMX16UP60B-2 | SP001537100   | IRAMX16UP60B-2 | SIP2    | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMS12UP60A   | SP001537108   | IRAMS12UP60A   | SIP 1   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAM630-1562F2 | SP001538554   | IRAM630-1562F2 | SIP2A   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMX16UP60A-2 | SP001538780   | IRAMX16UP60A-2 | SIP2    | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMS10UP60B-2 | SP001538798   | IRAMS10UP60B-2 | SIP 1   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAM136-1061A  | SP001539738   | IRAM136-1061A  | SIP1A   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAM136-3023B  | SP001540182   | IRAM136-3023B  | SIP3    | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMX20UP60A-2 | SP001540268   | IRAMX20UP60A-2 | SIP2    | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMS10UP60B   | SP001540288   | IRAMS10UP60B   | SIP 1   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMS06UP60A   | SP001540296   | IRAMS06UP60A   | SIP 1   | No Replacement    | No Replacement | No Replacement | No Replacement |

**Disclaimer:** The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

# Product Discontinuation



## EOL595

|                       |            |
|-----------------------|------------|
| ■ Last Order Date:    | 2017-12-31 |
| ■ Last Delivery Date: | 2018-6-30  |

| DISCONTINUED   |               |                |         | NEW (REPLACEMENT) |                |                |                |
|----------------|---------------|----------------|---------|-------------------|----------------|----------------|----------------|
| Device         | Ordering Code | OPN            | Package | Device            | Ordering Code  | OPN            | Package        |
| IRAMS10UP60A-2 | SP001540304   | IRAMS10UP60A-2 | SIP 1   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMX20UP60A   | SP001540410   | IRAMX20UP60A   | SIP2    | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMS06UP60B-2 | SP001540438   | IRAMS06UP60B-2 | SIP 1   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAM136-1061A2 | SP001544434   | IRAM136-1061A2 | SIP1A   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMT15TP60A-2 | SP001544618   | IRAMT15TP60A-2 | SIP1A   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMX30TP60A   | SP001544628   | IRAMX30TP60A   | SIP2    | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMT15TP60A   | SP001544636   | IRAMT15TP60A   | SIP1A   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAM630-1062F2 | SP001544644   | IRAM630-1062F2 | SIP2A   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAM136-1561A2 | SP001544666   | IRAM136-1561A2 | SIP1A   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMS10UP60B-S | SP001547506   | IRAMS10UP60B-S | SIP 1   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAM136-3063B2 | SP001547522   | IRAM136-3063B2 | SIP3    | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAM136-3063B  | SP001548244   | IRAM136-3063B  | SIP3    | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRAMS10UP60A   | SP001548466   | IRAMS10UP60A   | SIP 1   | No Replacement    | No Replacement | No Replacement | No Replacement |

**Disclaimer:** The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

# Product Discontinuation



## EOL595

|                       |            |
|-----------------------|------------|
| ■ Last Order Date:    | 2017-12-31 |
| ■ Last Delivery Date: | 2018-6-30  |

| DISCONTINUED   |               |               |         | NEW (REPLACEMENT) |                |                |                |
|----------------|---------------|---------------|---------|-------------------|----------------|----------------|----------------|
| Device         | Ordering Code | OPN           | Package | Device            | Ordering Code  | OPN            | Package        |
| IRDAKO726350B  | SP001540390   | IRDAKO726350B | SIP1A   | No Replacement    | No Replacement | No Replacement | No Replacement |
| IRDAKO705169   | SP001548446   | IRDAKO705169  | SIP1    | No Replacement    | No Replacement | No Replacement | No Replacement |
| 98-0290        | SP001543386   | 98-0290       | SIP1    | No Replacement    | No Replacement | No Replacement | No Replacement |
| 98-0291        | SP001536616   | 98-0291       | SIP1    | No Replacement    | No Replacement | No Replacement | No Replacement |
| 98-0308A       | SP001539456   | 98-0308A      | SIP1    | No Replacement    | No Replacement | No Replacement | No Replacement |
| IREBM630-1062F | SP001538862   | 98-0415       | SIP2A   | No Replacement    | No Replacement | No Replacement | No Replacement |

If you have any questions, please do not hesitate to contact your local sales office.

**Disclaimer:** The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!