



Product Change Notification

Current Date: 21-Jun-2017

TE Connectivity

Product Change Notification: P-17-014519**PCN Date:** 20-JUN-17**Customer:** Newark Electronics (167839)**Location:** Chicago**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Flag Relay Terminals, 20-16, 16-14, 14-10 & 12-10. 180 deg socket terminal

Description of Changes

Manufacturing location change. The plating process for the following Part Numbers will be transferred from "Outside Vendor" to our Landisville PA TE Connectivity manufacturing location.

Reason for Changes:

Dear Customer, as a result of our continuous strive for improving our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

Estimated Dates:**Last Order Date** (Obsolete Parts Only):**First Date To Ship** (Changed Parts Only):

29-DEC-2017

Last Ship Date (Obsolete Parts Only):**Last Date for Mixed Shipments:** (Changed Parts Only):

28-FEB-2018

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
53112-1	NO			"AMP-0-0053112-1", "F91441-000"			
53889-1	NO			"AMP-0-0053889-1", "D03571-000"			