

Product Change Notification (PCN)

| | | | |
|-----------------------------|---|-------------|----------------|
| PCN Number | 502631 | Date Issued | March 29, 2017 |
| Reason for Change | Packaging Method/Quantity Changing | | |
| Change Type Description | This letter is to inform you that the part(s) referenced in this notice will undergo packaging specification changes that may include new container sizes and quantities. No changes will be made to the product as a result of the packaging change. | | |
| Reason for Short Notice | Corrective Actions | | |
| Planned Implementation Date | March 31, 2017 | | |

Before Change

- Reel of Ribbon wire with UL processed wire respooled label



After Change

Overview

- This PCN is to replace PCN 501519 due to mistake of change type and missing detail of before and after
- REMOVE, UL PROCESSED WIRE RESPOOLED label Due to splitting process ribbon cable is not in UL PROCESSED WIRE RESPOOLED definition.

- Product Impact
 - no impact to any fit, form or function
- Part Number Impact
 - see attached impacted parts list



Molex Confidential Information



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:502631**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com