

## Product Change Notice

PCN#: EE-PCN17039

08/10/2017

### CLASSIFICATION OF CHANGE:

End of Life (EOL)

### DESCRIPTION OF CHANGE:

Various cut base ¼" x 1-¼" fuse blocks have reached EOL

### REASON FOR CHANGE:

Due to low sales volume and the availability of similar fuse blocks, the product has reached EOL

### EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

The recommended replacements of the S-8000 have a higher voltage and current rating than the cut base fuse blocks affected by this PCN. The recommended part numbers also have similar terminations to the EOL part numbers. Please see the S-8000 datasheet for further details.

### PARTS NUMBERS AFFECTED:

EOL Part Number	Recommended Replacement
2499	S-8203-1-R
2799	S-8101-1-R
2839	S-8202-1-R
4405	S-8001-1-R
4406	No Replacement
4407	S-8301-1-R
4574	No Replacement

### TIME SCHEDULE:

Last Time Buy Date: September, 30, 2017

Last Time Shipment Date: October 31, 2017

### SAMPLE AVAILABILITY:

Available upon request

### QUALIFICATION DATA:

Available upon request

### ISSUED BY:

Nick Stone

Product Manager – Circuit Protection

### CONTACT INFORMATION:

For questions or comments, please contact your local [Eaton sales representative](#).