



Product Change Notification

Current Date: 06-Oct-2017

TE Connectivity

Product Change Notification: P-17-014909

PCN Date: 04-OCT-17

Customer: DISTRIBUTOR NA (66666661)

Location: NO CITY PROVIDED

Agreement: 120513180001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Selected Straight Code 40 TINEL-LOCK Adapters (TXR40AB00 and TXRAC00)

Description of Changes

Additional manufacturing location for circular connector accessories products to establish additional capacity.

Reason for Changes:

Dear Customer, we hereby inform you that we are establishing an additional manufacturing locations, within existing TE Connectivity facilities, to improve customer service and reduce lead-time. The alternative manufacturing locations fully maintains quality, ability to supply and form-fit-function of the concern products. This manufacturing location operates under a certified quality management system in accordance with standard industry requirements.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	01-DEC-2017
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
002801-000	NO			6-1190021-3, TXR40AC00-0804AI			
004519-000	NO			5-1190034-5, TX40AC00-1007			
006069-000	NO			5-1190046-4, TX40AB00-1006			
019147-000	NO			6-1190149-1, TXR40AB00-1007AI			
031839-000	NO			9-1190246-1, TXR40AB00-1004BI			
038625-000	NO			7-1190296-4, TXR40AB00-1208BI			
091659-000	NO			9-1190671-4, TXR40AB00-1407BI			
093385-000	NO			1-1190685-0, TXR40AB00-1612BI			
102789-000	NO			2-1190752-7, TX40AB00-1206			
106443-000	NO			6-1190777-4, TXR40AB00-1408AI			
116025-000	NO			2-1190845-5, TXR40AB00-1206BI			
117085-000	NO			7-1190852-9, TXR40AC00-1205BI			
121571-000	NO			9-1190884-5, TXR40AB00-1610AI			
142565-000	NO			1-1191032-9, TX40AB00-1208			
146995-000	NO			3-1191062-0, TXR40AB00-1410AI			
150461-000	NO			9-1191087-1, TX40AB00-1408			
161565-000	NO			5-1191166-7, TXR40AC00-1205AI			
169269-000	NO			3-1191232-0, TXR40AB00-1407AI			
174283-000	NO			5-1191267-8, TX40AB00-1608			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
181065-000	NO			8-1191315-0, TX40AB00-1407			
182113-000	NO			4-1191323-9, TXR40AC00-1206AI			
227744-000	NO			2-1199123-9, TX40AC00-1004			
234305-000	NO			2-1191721-9, TX40AB00-1406			
254505-000	NO			1-1191863-8, TX40AC00-1208			
255295-000	NO			1191869-4, TX40AB00-1207			
259057-000	NO			3-1191895-6, TX40AC00-1410			
259725-000	NO			1-1191900-4, TXR40AB00-2012BI			
260027-000	NO			5-1191902-4, TX40AB00-1007			
293973-000	NO			7-1192227-3, TXR40AB00-1612AI			
317377-000	NO			6-1192404-1, TXR40AC00-1408BI			
330651-000	NO			2-1192498-1, TXR40AC00-1207BI			
364505-000	NO			6-1192733-2, TX40AB00-2012			
373419-000	NO			1192797-9, TXR40AC00-1208BI			
380615-000	NO			2-1192846-1, TXR40AC00-0804BI			
398665-000	NO			5-1192989-1, TX40AB00-0804			
415115-000	NO			8-1193128-1, TXR40AB00-0804BI			
417922-000	NO			1198096-7, TXR40AA00-1408AI			
423209-000	NO			1193187-1, TXR40AB00-0804AI			
423509-000	NO			2-1193189-8, TXR40AB00-1608BI			
458497-000	NO			7-1193439-7, TXR40AB00-1410BI			
461473-000	NO			5-1193461-6, TXR40AB00-1406BI			
472755-000	NO			8-1193541-5, TXR40AC00-1006BI			
489063-000	NO			2-1193659-7, TXR40AC00-1007AI			
489737-000	NO			7-1193663-4, TX40AB00-1612			
497361-000	NO			7-1193718-5, TXR40AB00-1208AI			
520728-000	NO			5-1200165-8, TX40AC00-1207			
535465-000	NO			2-1194204-4, TXR40AC00-1407AI			
552451-000	NO			6-1194366-3, TXR40AC00-1406AI			
554173-000	NO			5-1194375-5, TXR40AB00-1406AI			
596399-000	NO			3-1194717-2, TX40AC00-1006			
610299-000	NO			8-1194825-9, TX40AC00-1406			
627933-000	NO			8-1194971-4, TXR40AC00-1207AI			
629267-000	NO			2-1194981-0, TXR40AB00-1608AI			
644183-000	NO			8-1195088-8, TX40AC00-1206			
658819-000	NO			9-1195193-4, TXR40AB00-1006AI			
664529-000	NO			5-1195236-1, TXR40AB00-1206AI			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
675889-000	NO			1-1195315-0, TX40AB00-1812			
680789-000	NO			5-1195354-3, TXR40AC00-1208AI			
690189-000	NO			8-1195419-0, TXR40AC00-1006AI			
691787-000	NO			3-1195431-4, TX40AC00-1612			
701373-000	NO			2-1195504-8, TXR40AB00-1207BI			
723915-000	NO			2-1195659-3, TX40AB00-1205			
726974-000	NO			8-1195681-7, TXR40AB00-1004AI			
765249-000	NO			4-1195957-8, TX40AB00-1004			
776553-000	NO			9-1196045-2, TXR40AB00-1207AI			
778005-000	NO			9-1196055-5, TXR40AB00-1205AI			
799695-000	NO			7-1196182-8, TXR40AC00-1408AI			
807363-000	NO			2-1196255-3, TXR40AB00-1812BI			
817388-000	NO			3-1200164-5, TX40AC00-1205			
820593-000	NO			3-1196398-9, TXR40AB00-2012AI			
822313-000	NO			9-1196412-6, TXR40AB00-1005BI			
833129-000	NO			1-1196505-3, TX40AC00-1610			
835795-000	NO			7-1196524-6, TX40AC00-1812			
836025-000	NO			3-1196526-2, TX40AC00-0804			
850845-000	NO			7-1196633-8, TXR40AB00-1610BI			
861365-000	NO			5-1196710-6, TX40AB00-1610			
880407-000	NO			4-1196854-8, TX40AC00-1408			
886065-000	NO			4-1196894-2, TXR40AB00-1005AI			
903797-000	NO			5-1197023-3, TX40AC00-2012			
913885-000	NO			8-1197095-4, TXR40AB00-1812AI			
918713-000	NO			9-1197129-5, TXR40AC00-1005AI			
919073-000	NO			3-1197132-7, TXR40AC00-1004AI			
921653-000	NO			1197151-4, TXR40AB00-1006BI			
931313-000	NO			1197219-2, TXR40AA00-1410AI			
941793-000	NO			1-1197292-9, TXR40AB00-1007BI			
950899-000	NO			7-1197353-1, TX40AC00-1608			
978405-000	NO			2-1197559-3, TX40AB00-1005			
990207-000	NO			1-1197657-1, TXR40AB00-1408BI			
990779-000	NO			1197661-6, TX40AB00-1410			
D90475-000	NO			8-1200168-0, TX40AC00-1407			
E80544-000	NO			1200169-6, TX40AC00-1005			