

Attn.: _____

HIROSE ELECTRIC CO., LTD.
5-23, OSAKI 5-CHOME, SHINAGAWA-KU, TOKYO, JAPAN

Product Change Notification

We are writing today to inform you that we will make some changes as shown in the subject for the reason described below.

We request that you kindly offer your consent to this matter.

1	Products affected	Please refer to the attachment.
2	Replacement products	Please refer to the attachment.
3	Classification of change	For discontinued sales
4	Reason for change	For chronic supply instability of resin material manufacturer, SABIC, is expected to continue.
5	Date of final reception of orders for the current product	August 31, 2020
6	Date of final shipment of the current product	November 30, 2020
7	Date of your acknowledgement	By September 30, 2018

We kindly request that you inform Hirose business representative of your acknowledgement by the aforesaid date.

In the absence of a response by this date, please be advised that replacement product that described above will be delivered.

If you should have any questions, please feel free to contact a Hirose business representative. Your understanding and cooperation are highly appreciated.

■ Product List Business430-17025_Discontinued Sales of a Part of Products Using SABIC's Resin Material

No.	Current product		Replacement product	
	Product code	Product name	Product code	Product name
1	311-0239-3-40	BNC(75)J-PL72J-2PA(40)	311-0247-1-40 311-0269-4-41	BNC(75)J-PL72J-BPA(40) BNC(75)J-PL72J-BPA-1(41)
2	311-0246-9-40	BNC(75)J-PL72J(PA)(40)	311-0247-1-40 311-0269-4-41	BNC(75)J-PL72J-BPA(40) BNC(75)J-PL72J-BPA-1(41)
3	311-0303-0-40	BNC(75)J-PL72J-BPA-2(40)	311-0247-1-40 311-0269-4-41	BNC(75)J-PL72J-BPA(40) BNC(75)J-PL72J-BPA-1(41)
4	610-0801-6-71	HIF3B-16PA-2.54WB(71)	610-1505-9-71	HIF3BA-16PA-2.54WB(71)
5	610-0802-9-71	HIF3B-20PA-2.54WB(71)	610-1506-1-71	HIF3BA-20PA-2.54WB(71)
6	610-0803-1-71	HIF3B-26PA-2.54WB(71)	610-1507-4-71	HIF3BA-26PA-2.54WB(71)
7	610-0804-4-71	HIF3B-34PA-2.54WB(71)	610-1509-0-71	HIF3BA-34PA-2.54WB(71)
8	610-0805-7-71	HIF3B-40PA-2.54WB(71)	610-1510-9-71	HIF3BA-40PA-2.54WB(71)
9	610-0806-0-71	HIF3B-50PA-2.54WB(71)	610-1511-1-71	HIF3BA-50PA-2.54WB(71)
10	610-0807-2-71	HIF3B-64PA-2.54WB(71)	610-1515-2-71	HIF3BA-64PA-2.54WB(71)
11	610-0810-7-71	HIF3B-60PA-2.54WB(71)	610-1513-7-71	HIF3BA-60PA-2.54WB(71)
12	610-2103-0-71	HIF3BAW-20PA-2.54DS(71)	610-3504-7-00	HIF3MAW-20PA-2.54DS
13	610-2104-3-71	HIF3BAW-30PA-2.54DS(71)	610-3506-2-00	HIF3MAW-30PA-2.54DS
14	610-2105-6-71	HIF3BAW-50PA-2.54DS(71)	610-3509-0-00	HIF3MAW-50PA-2.54DS
15	610-2106-9-71	HIF3BBW-50PA-2.54DS(71)	610-3510-0-00	HIF3MBW-50PA-2.54DS
16	610-2107-1-71	HIF3BBW-60PA-2.54DS(71)	610-3512-5-00	HIF3MBW-60PA-2.54DS
17	610-2118-8-71	HIF3BAW-40PA-2.54DS(71)	610-3508-8-00	HIF3MAW-40PA-2.54DS
18	610-2119-0-71	HIF3BAW-16PA-2.54DS(71)	610-3503-4-00	HIF3MAW-16PA-2.54DS
19	112-1501-0-00	HR12-14R-20SDL	112-1502-2 00	HR12-14RA-20SDL
20	112-1502-2-01	HR12-14RA-20SDL(01)	112-1502-2 03	HR12-14RA-20SDL(03)
21	112-1504-8-01	HR12-14RA-20SC(01)	112-1504-8 00	HR12-14RA-20SC
22	302-0346-2-42	BNC-LR-PC-1B(42)	302-0346-2 40	BNC-LR-PC-1B(40)
23	561-0071-0-00	HIF2B-10D-2.54RA	561-0501-7 20	HIF2E-10D-2.54RA(20)
24	561-0027-8-00	HIF2B-20D-2.54RA	561-0504-5 20	HIF2E-20D-2.54RA(20)
25	561-0043-4-00	HIF2B-40D-2.54RA	561-0508-6 20	HIF2E-40D-2.54RA(20)
26	561-0047-5-00	HIF2B-50D-2.54RA	561-0509-9 20	HIF2E-50D-2.54RA(20)
27	561-0051-2-00	HIF2B-60D-2.54RA	561-0510-8 20	HIF2E-60D-2.54RA(20)
28	561-0073-5-00	HIF2B-10D-2.54RB	561-0601-1 20	HIF2E-10D-2.54RB(20)
29	561-0029-3-00	HIF2B-20D-2.54RB	561-0604-0 20	HIF2E-20D-2.54RB(20)
30	561-0037-1-00	HIF2B-30D-2.54RB	561-0606-5 20	HIF2E-30D-2.54RB(20)
31	561-0041-9-00	HIF2B-34D-2.54RB	561-0607-8 20	HIF2E-34D-2.54RB(20)
32	561-0045-0-00	HIF2B-40D-2.54RB	561-0608-0 20	HIF2E-40D-2.54RB(20)
33	561-0053-8-00	HIF2B-60D-2.54RB	561-0610-2 20	HIF2E-60D-2.54RB(20)
34	562-0071-6-00	HIF3-10P-2.54DS	610-0091-2 71	HIF3BA-10PA-2.54DS(71)
35	562-0002-3-00	HIF3-26P-2.54DS	610-0095-3 71	HIF3BA-26PA-2.54DS(71)
36	562-0003-6-00	HIF3-34P-2.54DS	610-0097-9 71	HIF3BA-34PA-2.54DS(71)
37	562-0004-9-00	HIF3-40P-2.54DS	610-0098-1 71	HIF3BA-40PA-2.54DS(71)
38	562-0072-9-00	HIF3-10P-2.54DSA	610-0111-8 71	HIF3BA-10PA-2.54DSA(71)
39	562-0076-0-00	HIF3-16P-2.54DSA	610-0113-3 71	HIF3BA-16PA-2.54DSA(71)
40	562-0007-7-00	HIF3-26P-2.54DSA	610-0115-9 71	HIF3BA-26PA-2.54DSA(71)
41	562-0009-2-00	HIF3-40P-2.54DSA	610-0118-7 71	HIF3BA-40PA-2.54DSA(71)
42	562-0010-1-00	HIF3-50P-2.54DSA	610-0119-0 71	HIF3BA-50PA-2.54DSA(71)
43	562-0052-1-04	HIF3-60P-2.54DSA(04)	610-0120-9 05	HIF3BA-60PA-2.54DSA(75)
44	562-0494-0-00	HIF3C-10D-2.54C	610-1041-0 00	HIF3BA-10D-2.54C
45	562-0495-2-00	HIF3C-16D-2.54C	610-1042-2 00	HIF3BA-16D-2.54C
46	562-0200-7-00	HIF3C-50D-2.54C	610-1048-9 00	HIF3BA-50D-2.54C
47	617-0020-9-00	HIF3G-20P-2.54DS	620-0020-1 71	A2-20PA-2.54DS(71)
48	617-0090-4-00	HIF3G-20P-2.54DSA	620-0070-0 71	A2-20PA-2.54DSA(71)
49	588-0247-3-71	MA18A-44DA-2DSA(71)	621-0766-0 71	A3D-44DA-2DSE(71)
50	588-0253-6-71	MA18A-44DA-2DSC(71)	621-0766-0 71	A3D-44DA-2DSE(71)
51	676-1012-3-00	DF33-6RDS-3.3	676-1126-2 00	DF33C-6RDS-3.3
52	676-1013-6-00	DF33-8RDS-3.3	676-1127-5 00	DF33C-8RDS-3.3
53	676-1014-9-00	DF33-10RDS-3.3	676-1128-8 00	DF33C-10RDS-3.3
54	676-1015-1-00	DF33-12RDS-3.3	676-1129-0 00	DF33C-12RDS-3.3
55	676-1030-5-00	DF33-6RS-3.3	676-1145-7 00	DF33C-6RS-3.3
56	755-0003-4-35	GT5-2/1S-R(35)	755-0003-4 00	GT5-2/1S-R
57	755-0005-0-35	GT5-1PP-HU(35)	755-0005-0 10	GT5-1PP-HU(10)
58	760-0001-4-71	GT10-16DP-DS(71)	760-0001-4 70	GT10-16DP-DS(70)
59	763-0005-4-71	GT13-1P-DS(71)	763-0005-4 70	GT13-1P-DS(70)
60	321-6184-3-00	NFLUFLVHF-04N1TV-A88.5CLG		
61	321-6185-6-00	NFLUFLVHF-04N2TV-A90ALG		
62	562-0190-5-00	HIF3-6P-2.54DS		
63	104-0419-0-71	HA16PRM-3SD(71)		
64	104-0436-0-71	HA16PRQ-3SE(71)		
65	104-0470-8-71	HA16PRM-3SI(71)		
66	108-0136-1-71	HR08N-31PA(71)		
67	109-2004-8-71	RM215TR-10SC(71)		
68	109-5005-7-71	RM515EPA-10PC(71)		
69	109-5006-0-71	RM515ERB-10SD(71)		
70	112-0511-8-71	HR12-10RC-10SDL(71)		

We're sorry to cause any inconvenience to you, but we have no plan to sell replacement products.

No.	Current product		Replacement product	
	Product code	Product name	Product code	Product name
71	112-0804-6-71	HR12-10RH-10SD(71)		
72	113-0029-7-01	RP5-19R-14SC(01)		
73	302-0385-4-40	BNC(75)-BPJ-1.5CV-4(40)		
74	312-0116-0-00	HRPI-H2-PA		
75	312-0117-2-00	HRPI-H1-PA		
76	313-0228-0-42	TWT2-P-4(42)		
77	313-0324-3-00	TWT2-TA-JJJ-2		
78	313-0327-1-40	TWT2-P-2-2(40)		
79	313-0542-4-40	TWPOD4-P(40)		
80	321-0011-0-02	TNCBPJD-U.FLHF-088K2T-40		
81	321-0035-0-01	H.FL75-2LPG084N1-A-TG80B		
82	321-0057-0-01	H.FL6G-LP-084J-A1-129.4YK		
83	321-0140-0-01	TWBPJ2-UFLHF6-088K2TAE150		
84	321-0144-0-01	E.FL-LP-066N1-A-11-(225)A		
85	321-0187-0-28	U.FL-LP6-088K1T-A-(75)		
86	321-0187-0-29	U.FL-LP6-088K1T-A-(155)		
87	321-0187-0-30	U.FL-LP6-088K1T-A-(210)		
88	321-0286-0-28	WFL-2LPHF6-04N2TV-AC-82E		
89	321-0328-0-00	U.FL-2LP-088SD2PD-AT-189		
90	321-0329-0-00	U.FL-2LP-088SD2PD-AT-225		
91	321-0335-0-01	UFL-LP6-068N1T-11-400D		
92	321-0378-0-11	N.FL-LP-04N2-A-(130)		
93	321-0385-0-10	W.FL-LPGHF-062N2D-A-120		
94	321-1280-0-55	H.FL-LP-FHSB-A-(281)A		
95	321-1281-2-56	H.FL-2LP-FHSB-A-(132)		
96	321-1554-3-33	E.FL-2LP-04-A-(220)		
97	321-1554-3-34	E.FL-2LP-04-A-(42)A		
98	321-1567-5-26	H.FL-2LP-111-A-(95)		
99	321-1821-8-04	H.FL-2LP-066H-A-(280)A		
100	321-1908-4-21	H.FL-LP(A)-FHSB-A-(210)		
101	321-1908-4-41	H.FL-LP(A)-FHSB-A-(81.5)A		
102	321-1908-4-42	H.FL-LP(A)-FHSB-A-(59)A		
103	321-1908-4-43	H.FL-LP(A)-FHSB-A-(147)A		
104	321-2151-2-26	H.FL75-2LP-084H-A-1200		
105	321-2162-9-27	U.FL-LP-066H-A-(85)		
106	321-2942-8-01	N.UM-LP-1.5DW-A-(100)		
107	321-2942-8-02	N.UM-LP-1.5DW-A-(200)		
108	321-2942-8-03	N.UM-LP-1.5DW-A-(300)		
109	321-2942-8-04	N.UM-LP-1.5DW-A-(400)		
110	321-2942-8-05	N.UM-LP-1.5DW-A-(500)		
111	321-3022-5-28	E.FL-2LP-0733-A-(558)		
112	321-3022-5-29	E.FL-2LP-0733-A-(550)		
113	321-3196-6-42	U.FL-2LP-088K1T-A-(87)		
114	321-3196-6-43	U.FL-2LP-088K1T-A-(142)		
115	321-3196-6-58	U.FL-2LP-088K1T-A-(200)B		
116	321-3196-6-62	U.FL-2LP-088K1T-A-(62)		
117	321-3196-6-63	U.FL-2LP-088K1T-A-(72)		
118	321-3196-6-64	U.FL-2LP-088K1T-A-(147)		
119	321-3279-1-73	U.FL-2LP-068N1-A-(87)		
120	321-3279-1-74	U.FL-2LP-068N1-A-(142)		
121	321-3279-1-77	U.FL-2LP-068N1-A-(255)		
122	321-3362-3-29	U.FL-LP-066N1-A-(310)		
123	321-3362-3-37	U.FL-LP-066N1-A-(1100)		
124	321-3362-3-38	U.FL-LP-066N1-A-(515)		
125	321-3362-3-42	U.FL-LP-066N1-A-(930)		
126	321-3372-7-74	U.FL-2LP-04N1-A-(230)		
127	321-3728-3-19	TWPOD4-P.P40-(2300)N2		
128	321-4551-1-01	BPJA-UMLP41-196-W1-150RS		
129	321-4551-1-02	BPJA-UMLP41-196-W2-150RS		
130	321-4551-1-03	BPJA-UMLP41-196-W3-150RS		
131	321-4551-1-04	BPJA-UMLP41-196-W4-170RS		
132	321-4579-0-01	U.FL-LP-088K2T-A-27-(152)		
133	321-4603-3-18	N.FL-LP-04N1-A-(130)		
134	321-4615-2-29	U.FL-2LP-04N1T-A-(390)		
135	321-4630-6-00	W.FL-LPHF-04N2T-20-28.6		
136	321-4805-8-01	W.FL-2LPHF-03N1T-AC76SM		
137	321-4806-0-04	U.FL-LP-068NU2T-12-(45)A		
138	321-4807-3-04	U.FL-LP-068NU1T-12-(53)A		
139	321-4808-6-01	U.FL-LP-068NU1T-17-200A		
140	321-4809-9-01	U.FL-LP-068NU2T-17-240A		

We're sorry to cause any inconvenience to you, but we have no plan to sell replacement products.

No.	Current product		Replacement product	
	Product code	Product name	Product code	Product name
141	321-4841-1-02	U.FL-2LP-066JU1-AA-(540)A		
142	321-4932-5-00	WFL-2LPGHF-062DA2-AC52.6E		
143	321-4933-8-00	WFL-2LPGHF062N2D-ACSE64BS		
144	321-4937-9-00	W.FL-2LPHF-04TA1C-A-87.5E		
145	321-4938-1-00	W.FL-2LPHF-04TA1C-A-42.5E		
146	321-5068-7-01	UFL-V6-04K1TTFV-A12-310.7		
147	321-5072-4-01	WFL-2LPHF-04K2T-A-SE25		
148	321-5073-7-00	WFLHF-XFL-2LP04K2T-ACSE56		
149	321-5075-2-00	W.FL-2LPHF-04TA2C-A-25.5E		
150	321-5145-6-02	UFLVHF6-04K2TTFVA13-94.5		
151	321-5146-9-02	UFLVHF6-04K5TTFVA12-141		
152	321-5149-7-00	WFL-2LPGHF062DA2-AMT36.5R		
153	321-5163-8-00	U.FL-2LP(V)-04N1-A-80GC		
154	321-5165-3-02	H.FL75-2LP-084N2-A-120		
155	321-5173-1-02	WFL-2LPGHF-062N2D-A63.5HT		
156	321-5173-1-03	WFL-2LPGHF-062N2D-A19.5HT		
157	321-5174-4-01	N.FL-2LP-04N1-AC-N-100.3A		
158	321-5179-8-00	UFLVWFLHF-2LP04K1TACSE66M		
159	321-5191-3-05	U.FL-LP-088N2T-A-19-90F		
160	321-5191-3-06	U.FL-LP-088N2T-A-19-200F		
161	321-5192-6-03	BNCPJ-H.FLA-111-A-400RS		
162	321-5214-7-00	N.FL-2LP-04N1-AC-NA-98.5A		
163	321-5232-9-00	UFL-2LPVHF-04N1TC-A88ABLG		
164	321-5233-1-00	UFLVWFLHF04N1TC-A86ELG		
165	321-5234-4-00	UFLVWFLHF04N2TC-A84CLG		
166	321-5235-7-00	UFL-2LPVHF-04N1TC-A88ACLG		
167	321-5243-5-00	UFL-2LPVHF-04N1TC-A86NLG		
168	321-5244-8-00	UFL-2LPVHF-04N1TC-A92AFLG		
169	321-5245-0-00	UFL-2LPVHF-04N2TC-A88JLG		
170	321-5247-6-01	UFLVHF6-04K2TTFVA14-345		
171	321-5248-9-01	UFL-LPVHF6-04N2-A12-345		
172	321-5249-1-00	WFL-2GHF6-062N2D-ASE88.8S		
173	321-5250-0-00	UFLVWFLHF6-04N1TVACSE66M		
174	321-5255-4-00	U.FL-ELM24G3-088K2T-B152		
175	321-5256-7-00	U.FL-ELM50G3-088K2T-B152		
176	321-5257-0-00	E.FL-LP-04N1-A-91-(50)		
177	321-5258-2-00	WFL-2LPGHF-062DA2-AMT95AC		
178	321-5259-5-00	WFL-LPGHF-062DA2-A11-44E		
179	321-5305-0-00	UFL-2LPVHF-04N1TC-A97ANLG		
180	321-5344-2-28	U.FL-LP-088K5T-A-(500)D		
181	321-5345-5-28	U.FL-LP-088K6T-A-(500)D		
182	321-5348-3-28	WFL-2LPHF6-04K1TV-A-52.5E		
183	321-5349-6-00	UFL-2LPVHF04N1TC-A100ARLG		
184	321-5350-5-00	UFL-2LPVHF-04N1TC-A92ASLG		
185	321-5352-0-00	WFL-2LPGHF062N2D-ASE66.5S		
186	321-5353-3-28	UFL-2LPVHF6-04K1TV-AC-56E		
187	321-5363-7-28	WFL-2LPHF6-04N1TV-A-71.5E		
188	321-5363-7-29	WFL-2LPHF6-04N1TV-A-33.5E		
189	321-5363-7-31	WFL-2LPHF6-04N1TV-A-20.8E		
190	321-5363-7-32	WFL-2LPHF6-04N1TV-A-73E		
191	321-5363-7-34	WFL-2LPHF6-04N1TV-A-62E		
192	321-5363-7-35	WFL-2LPHF6-04N1TV-A-64E		
193	321-5363-7-36	WFL-2LPHF6-04N1TV-A-66E		
194	321-5363-7-37	WFL-2LPHF6-04N1TV-A-68E		
195	321-5363-7-39	WFL-2LPHF6-04N1TV-A-72E		
196	321-5363-7-40	WFL-2LPHF6-04N1TV-A-74E		
197	321-5363-7-41	WFL-2LPHF6-04N1TV-A-76E		
198	321-5363-7-42	WFL-2LPHF6-04N1TV-A-78E		
199	321-5363-7-44	WFL-2LPHF6-04N1TV-A-82E		
200	321-5363-7-45	WFL-2LPHF6-04N1TV-A-84E		
201	321-5363-7-46	WFL-2LPHF6-04N1TV-A-86E		
202	321-5363-7-47	WFL-2LPHF6-04N1TV-A-88E		
203	321-5363-7-49	WFL-2LPHF6-04N1TV-A-92E		
204	321-5363-7-50	WFL-2LPHF6-04N1TV-A-94E		
205	321-5363-7-51	WFL-2LPHF6-04N1TV-A-96E		
206	321-5363-7-52	WFL-2LPHF6-04N1TV-A-98E		
207	321-5370-2-00	UFL-2LPVHF-04N2TC-A93MLG		
208	321-5371-5-28	WFL-2LPHF6-04N1TV-AC-23EX		
209	321-5371-5-29	WFL-2LPHF6-04N1TV-AC-20E		
210	321-5388-8-01	UFLVHF6-04K9TTFVA14-333		

We're sorry to cause any inconvenience to you, but we have no plan to sell replacement products.

No.	Current product		Replacement product	
	Product code	Product name	Product code	Product name
211	321-5400-1-28	N.FL-2LP6-04N1T-A-(63.2)B		
212	321-5400-1-29	N.FL-2LP6-04N1T-A-(82)B		
213	321-5401-4-28	N.FL-2LP6-04N1T-AC-57.5B		
214	321-5408-3-00	WFL-2GHF-062N2D-AC68HT		
215	321-5409-6-01	U.FL-LJ-088K1T-A-11-37B		
216	321-5411-8-01	U.FL-2LP-088N3T-A-(110)F		
217	321-5436-9-01	SMARBPJ-UFL-088N2PD-A-50		
218	321-5436-9-02	SMARBPJ-UFL-088N2PD-A-100		
219	321-5436-9-03	SMARBPJ-UFL-088N2PD-A-150		
220	321-5436-9-04	SMARBPJ-UFL-088N2PD-A-200		
221	321-5436-9-05	SMARBPJ-UFL-088N2PD-A-250		
222	321-5436-9-06	SMARBPJ-UFL-088N2PD-A-300		
223	321-5436-9-07	SMARBPJ-UFL-088N2PD-A-350		
224	321-5436-9-08	SMARBPJ-UFL-088N2PD-A-400		
225	321-5436-9-09	SMARBPJ-UFL-088N2PD-A-450		
226	321-5436-9-10	SMARBPJ-UFL-088N2PD-A-500		
227	321-5833-9-02	U.FL-LP-088K2T-A-42-(88)D		
228	321-5835-4-02	TNCPJ-U.FL-088N2PD-83.8RS		
229	321-5836-7-28	U.FL-LP-088N2PD-A-(185)		
230	321-5840-4-26	H.FL75-2LPG-084N2-400A		
231	321-5857-7-00	UFL-2LPVHF-04N1TC-A76ALG		
232	321-5858-0-00	UFLVWFLHF04N2TC-A85.5ALG		
233	321-5860-1-01	U.FL-LP-088N2T-A-21-(80)		
234	321-5860-1-02	U.FL-LP-088N2T-A-21-(160)		
235	321-5860-1-03	U.FL-LP-088N2T-A-21-(130)		
236	321-5870-5-00	UFL-2LPVHF04N1TV-A91PHW		
237	321-5872-0-01	U.FL-LP-066N2-A-25-(40)D		
238	321-5876-1-02	HRMBPJ-N.FL-04N1-A-120RS		
239	321-5883-7-00	U.FL-2LP(V)-04N1-A-T-115		
240	321-5886-5-00	NFL-2LPHF6-04K2TV-A-RM68G		
241	321-5889-3-00	UFL-2LPVHF-04N2TC-A73ALG		
242	321-5890-2-00	UFL-2LPVHF-04N1TC-A70BLG		
243	321-5891-5-01	HRMJ-U.FL-066N1-A-T-180RS		
244	321-5891-5-02	HRMJ-U.FL-066N1-A-T-305RS		
245	321-5900-4-01	U.FL-LP-068NU2T-A-17-500		
246	321-5901-7-01	U.FL-LP-088NU5T-A11-555TB		
247	321-5902-0-01	U.FL-LP-068NU5T-AA11-450A		
248	321-5903-2-01	U.FL-2LP-066HU-A-(100)		
249	321-5904-5-01	U.FL-2LP(V)-04NU1-C-(40)		
250	321-5905-8-01	H.FL-2LP(A)-111-AC-(80)		
251	321-5905-8-02	H.FL-2LP(A)-111-AC-(225)B		
252	321-5944-0-08	U.FL-2LP-04K5T-A-(100)		
253	321-5947-8-01	UFLVHF6-04K2TTFVA20-151		
254	321-5953-0-28	U.FL-LP-04K1TV-A-(55)		
255	321-5956-9-01	HRMP-U.FL-066N1-A-200RS		
256	321-5980-3-01	U.FL-LP-068N2T-A13-73HD		
257	321-5986-0-01	TBPJA-UFL068N1T-A-T-370RS		
258	321-5990-7-01	UFLVHF6-04K2TTFVA22-69		
259	321-5990-7-03	UFLVHF6-04K2TTFVA22-63.5		
260	321-5996-3-02	UFLVHF6-04K1TTFVA16-63.5		
261	321-5996-3-03	UFLVHF6-04K1TTFVA16-33.5		
262	321-6007-8-01	U.FL-LP-068N2T-A16-76HD		
263	321-6008-0-00	U.FL-2LP-068N1-A-T-150FJT		
264	321-6009-3-06	UFL-2LPVHF-04N1TV-A60HW		
265	321-6009-3-07	UFL-2LPVHF-04N1TV-A70HW		
266	321-6010-2-01	U.FL-LP-068N2T-A12-60.5HD		
267	321-6011-5-01	U.FL-LP-068N2T-A15-210HD		
268	321-6016-9-01	U.FL-LP-088N1T-(207)D		
269	321-6016-9-28	U.FL-LP-088N1T-(360)D		
270	321-6032-5-01	E.FL-2LP-066J1-AA-(75.1)A		
271	321-6055-0-01	UFL-VHF-04N1TV-A11-78.8HW		
272	321-6055-0-02	UFL-VHF-04N1TV-A11-53HW		
273	321-6056-3-01	UFL-2LPVHF-04N2TV-A98HW		
274	321-6083-6-01	U.FL-LP-068N2T-A-35-(100)		
275	321-6085-1-00	U.FL-2LP-068N1T-T-(42)D		
276	321-6087-7-27	W.FL2-LP-04N1TV-A-(310)		
277	321-6101-6-00	U.FL-2LP-068N1T-A-T-50D		
278	321-6135-8-01	UFLVHF6-04K4TTFVA13-277		
279	321-6136-0-01	UFLVHF6-04K6TTFVA15-314.7		
280	321-6136-0-02	UFLVHF6-04K6TTFVA15-307.7		

We're sorry to cause any inconvenience to you, but we have no plan to sell replacement products.

No.	Current product		Replacement product	
	Product code	Product name	Product code	Product name
281	321-6149-2-01	UFLVHF6-04K6TTFFVA16-307.7		
282	321-6154-2-01	UFLVHF6-04K4TTFFVAA1-279.3		
283	321-6155-5-01	UFLVHF6-04K6TTFFVAA1-309		
284	321-6178-0-00	UFL-LPLJ-088N1T-A-T-325AF		
285	321-6179-3-00	UFL-LPLJ-088N2T-A-T420AF2		
286	321-6204-9-09	W.FL2-LP-04N2-A-(110)		
287	321-6206-4-01	U.FL-LP-066N1-A-55-(30)D		
288	321-6522-4-01	H.FL75-2LPG084N2-A-TG300A		
289	321-6529-3-01	HRMJ-UFL-088K2T-A-450RS		
290	321-6534-3-01	HRMBPJ-UFL066J1-AE-T75CS		
291	321-6534-3-02	HRMBPJ-UFL066J1-AE-T100CS		
292	321-6607-5-01	H.FL6G-LP-084H-A-129.4YK		
293	321-6617-9-01	HRMBPJ-UFL-066J1-AE-T-75		
294	321-6617-9-02	HRMBPJ-UFL-066J1-AE-T-100		
295	321-6625-7-01	HRMJ-H.FL-FHSB-A-290ARS		
296	330-0211-2-40	PO51E-3P-PA-A(40)		
297	330-0212-5-00	PO51E-3S-HA-A		
298	330-0219-4-40	PO51E-3TMP-PA-A(40)		
299	331-0506-2-01	H.FL-LP-1.25C(01)		
300	506-0035-4-00	CR6-14S-3.96E		
301	535-0046-6-00	EC1B-5PG-2.5DS		
302	535-0061-0-00	EC1A-5PG-2.5DSA		
303	541-0155-3-05	DF1-SP(05)		
304	547-0226-8-55	MDF7N-24DP-2.54DS(55)		
305	547-0406-0-05	MDF83-10S-5.08DSA(05)		
306	547-0498-8-05	MDF71-4CP-4A(05)		
307	548-0044-7-01	MCR29-80D-3.17W(01)		
308	561-0059-4-00	HIF2B-16-2.54RA		
309	562-0092-6-00	HIF3-マルチラング(30)		
310	562-0097-0-00	HIF3-10CL		
311	562-0102-8-00	HIF3-34CL		
312	562-0104-3-00	HIF3-50CL		
313	562-0189-6-00	HIF3C-6D-2.54C		
314	562-0271-5-00	HIF3-マルチラング(34)		
315	562-0273-0-00	HIF3-マルチラング(50)		
316	572-1066-9-00	FX2-52PA-1.27DSL		
317	572-2651-4-62	FX2-20P-1.27DSL(62)		
318	581-0101-3-05	PCN6-10PA-2.5DS(05)		
319	581-0140-5-01	PCN6-15S-2.5C(01)		
320	581-0178-8-05	PCN6B-5P-2.5DS(05)		
321	581-0182-5-02	PCN6B-22P-2.5DS(02)		
322	581-0284-5-72	PCN5D-13STA-1.27DS(72)		
323	581-0285-8-72	PCN5D-23STA-1.27DS(72)		
324	581-0286-0-72	PCN5D-31STA-1.27DS(72)		
325	581-0289-9-72	PCN5D-65STA-1.27DS(72)		
326	581-0291-0-72	PCN5D-100STA-1.27DS(72)		
327	581-0293-6-00	PCN5D-23PT-1.27DS		
328	581-0294-9-00	PCN5D-31PT-1.27DS		
329	581-0299-2-00	PCN5D-100PT-1.27DS		
330	581-0333-9-00	PCN5D-23ST-1.27DS		
331	581-0334-1-00	PCN5D-31ST-1.27DS		
332	581-0335-4-00	PCN5D-45ST-1.27DS		
333	583-0494-0-73	PCN10MLA-39S-2.54DSA(73)		
334	583-0500-1-73	PCN10MLA-96S-2.54DSA(73)		
335	583-1038-7-00	PCN11M-128P-2.54C		
336	583-1039-0-00	PCN11M-タンパン(128)		
337	583-1041-1-00	PCN11M-タンパン(64)		
338	583-1042-4-00	PCN11M-タンパン(36)		
339	583-1042-4-01	PCN11M-TANSIBAN(36)		
340	583-1042-4-04	PCN11M-TANSHIBAN(36)(04)		
341	583-1203-1-00	PCN11M-タンパン(64A)		
342	583-1203-1-31	PCN11M-TANSIBAN(64A)(31)		
343	583-1219-1-77	PCN11ME-128S-2.54DS(77)		
344	583-1229-5-00	PCN11MF-タンパン(64)		
345	583-1230-4-00	PCN11MF-64P-2.54C		
346	583-1235-8-00	PCN11MA-タンパン(128)		
347	583-1236-0-00	PCN11MA-タンパン(96A)		
348	583-1240-8-77	PCN11MG-128S-2.54DS(77)		
349	583-1242-3-77	PCN11MG-64S-2.54DS(77)		
350	583-1246-4-00	PCN11M-タンパン(128B)		

We're sorry to cause any inconvenience to you, but we have no plan to sell replacement products.

No.	Current product		Replacement product	
	Product code	Product name	Product code	Product name
351	583-1250-1-00	PCN11M-タンパン(64B)		
352	584-0790-0-70	PA-85790(70)		
353	588-0192-3-71	MIF35-16PA-2.54DSA(71)		
354	588-0223-5-71	MIF68-50DA-1.27DSAL(71)		
355	588-0290-2-00	MIF81-40PD		
356	588-0323-0-71	MA18M-50DA-2DSB(71)		
357	588-0388-5-00	MA44-10D-2C		
358	588-0394-8-71	MIF96-45S(2)-0.5R(71)		
359	589-0167-2-00	MCN45-128P-2.54PFB		
360	589-0168-5-00	MCN45-128(64)P-2.54PFB		
361	589-0195-8-00	MCN51-30P3-DS		
362	589-0196-0-00	MCN51-30S3-PFA		
363	589-0200-6-00	MCN51-8S2-PFA		
364	589-0202-1-00	MCN51-8P2-DS		
365	610-0074-3-71	HIF3B-26PA-2.54DSA(71)		
366	610-0161-6-71	HIF3BC-10PA-2.54DSA(71)		
367	610-0594-3-00	HIF3B-26D-2.54R(C)		
368	610-1105-0-71	HIF3BAL-20PA-2.54DSA(71)		
369	610-1106-3-71	HIF3BAL-26PA-2.54DSA(71)		
370	610-1108-9-71	HIF3BAL-34PA-2.54DSA(71)		
371	610-1109-1-71	HIF3BAL-40PA-2.54DSA(71)		
372	610-1110-0-71	HIF3BAL-50PA-2.54DSA(71)		
373	610-1402-6-71	HIF3BAJ-16PA-DSL(71)		
374	617-0050-0-00	HIF3G-50P-2.54DS		
375	617-0120-3-00	HIF3G-50P-2.54DSA		
376	617-0143-9-00	HIF3G-15S-2.54C		
377	618-0151-3-71	HIF3H-130DB-2.54DS(71)		
378	618-0212-6-71	HIF3H-130PB-2.54DSA(71)		
379	640-0018-4-72	IC1FB-68PD-1.27DS-EJ(72)		
380	640-1409-7-00	IC14-G-PEJR		
381	640-1409-7-72	IC14-G-PEJR(72)		
382	640-1411-9-00	IC14A-G-PEJR		
383	640-1412-1-00	IC14A-G-PEJL		
384	640-1413-4-10	IC14B-G-PEJR(10)		
385	641-0192-8-03	IT1-168P/28-19H(03)		
386	641-2151-1-03	IT2-380PS-15H(03)		
387	641-2155-2-13	IT2-380PS-17H(13)		
388	641-2251-6-03	IT2-380PS-25H(03)		
389	641-2300-0-03	IT2-380PS-35H(03)		
390	641-2305-3-03	IT2-380PS-32.2H(03)		
391	643-0037-8-00	PCN21-S-CK(A)		
392	643-0038-0-00	PCN21-S-CK(B)		
393	643-0039-3-00	PCN21-P-CK(A)		
394	643-0040-2-00	PCN21-P-CK(B)		
395	703-0039-2-42	SMPO-HOUSING(42)		
396	703-0039-2-43	SMPO-HOUSING(43)		
397	703-0054-6-00	SMPOHAUJINGUG		
398	703-0054-6-02	SMPOHAUJINGUG(02)		
399	703-0054-6-05	SMPOHAUJINGUG(05)		
400	703-0064-0-00	SMPO 7レ-ム		
401	703-0068-0-00	SMPO-STOPPER-A		
402	703-0069-3-00	SMPO-KEVLER-STOPPER		
403	704-0024-1-51	HSC2-4A(51)		
404	704-0026-7-00	HSC-P-T		
405	704-0266-0-03	HSC2-8SR-1(03)		
406	704-0266-0-13	HSC2-8SR-1(13)		
407	704-0267-3-51	HSC2-FK-A125(51)		
408	704-0267-3-56	HSC2-FK-A125(56)		
409	704-0268-6-51	HSC2-FK-A126(51)		
410	704-0268-6-56	HSC2-FK-A126(56)		
411	704-0269-9-51	HSC2-FK-A1255(51)		
412	704-0269-9-56	HSC2-FK-A1255(56)		
413	704-0270-8-01	HSC2-8SR-D1(01)		
414	704-0290-5-01	HSC2-4A-D1(01)		
415	704-0291-8-03	HSC-SR-2(03)		
416	704-0291-8-51	HSC-SR-2(51)		
417	704-0291-8-52	HSC-SR-2(52)		
418	704-0292-0-06	HSC-SR-D2(06)		
419	704-0293-3-51	HSCH-2SR-1(R)(51)		
420	704-0294-6-01	HSCH-2SR-D1(R)(01)		

We're sorry to cause any inconvenience to you, but we have no plan to sell replacement products.

No.	Current product		Replacement product	
	Product code	Product name	Product code	Product name
421	704-0295-9-03	HSCF-2SR-2(P)(03)		
422	704-0295-9-51	HSCF-2SR-2(P)(51)		
423	704-0295-9-52	HSCF-2SR-2(P)(52)		
424	704-0300-7-03	HSCH-2SR-3(R)(03)		
425	704-0311-3-03	HSC2-4SR-1(03)		
426	704-0311-3-51	HSC2-4SR-1(51)		
427	704-0311-3-52	HSC2-4SR-1(52)		
428	704-0312-6-01	HSC2-4SR-D1(01)		
429	704-0318-2-51	HSC2-8SR-2(51)		
430	704-0320-4-03	HSC-SR-1(03)		
431	704-0320-4-51	HSC-SR-1(51)		
432	704-0321-7-02	HSC-SR-D1(02)		
433	704-0407-0-56	HSC2-FK2-A125(56)		
434	704-0408-3-56	HSC2-FK2-A1255(56)		
435	704-0409-6-56	HSC2-FK2-A126(56)		
436	704-0450-0-01	HSC2-10SR-2(01)		
437	704-0450-0-51	HSC2-10SR-2(51)		
438	704-0466-0-00	HSC2-10SR-3		
439	706-0593-0-00	CA04AF04K-SPM-A-0.2M		
440	707-0033-1-65	HRPI-BPH2-C1(65)		
441	707-0034-4-61	HRPI-BPH2-C2(61)		
442	707-0038-5-61	HRPI-BPH2-B1-E(61)		
443	707-0047-6-40	HRPI-H4-HA-F-B(40)		
444	707-0047-6-41	HRPI-H4-HA-F-B(41)		
445	710-0048-1-61	HMUA-2P2-H1(61)		
446	710-0059-8-00	HMUA-DP-1		
447	710-0131-3-00	HMUA-DP-2		
448	710-0132-6-01	HMUA-DP-3(01)		
449	710-0135-4-40	HMUB-DP-1(40)		
450	710-0247-8-00	HMUA-2A-40A-4-S2		
451	710-0259-7-00	HMUA-2AH-4-HA		
452	755-0008-8-70	GT5-2/1PP-HU(70)		
453	755-0011-2-70	GT5-2428/F3.3-5PCF(70)		
454	755-0012-5-70	GT5-2428/F3.3-5SCF(70)		
455	755-0014-0-70	GT5-2/1P-DS(70)		
456	755-0015-3-70	GT5-30/F3.3-5PCF(70)		
457	755-0016-6-70	GT5-30/F3.3-5SCF(70)		
458	755-0023-1-70	GT5-2428/F4-5PCF(70)		
459	755-0024-4-70	GT5-2428/F4-5SCF(70)		
460	755-0033-5-70	GT5-2022/F3.3-5PCF(70)		
461	755-0034-8-70	GT5-2022/F3.3-5SCF(70)		
462	755-0035-0-70	GT5-2022/F4-5PCF(70)		
463	755-0036-3-70	GT5-2022/F4-5SCF(70)		
464	755-0053-2-70	GT5-2022/F3.3-3.8PCF(70)		
465	755-0054-5-70	GT5-2022/F3.3-3.8SCF(70)		
466	755-0061-0-70	GT5-2P-DS(A)(70)		
467	755-0062-3-70	GT5-2P-DS(B)(70)		
468	755-0067-7-70	GT5L-30/1.6-2.9PCF(70)		
469	755-0079-6-70	GT5L-2428/1.6-2.5PCF(70)		
470	755-0101-3-70	GT5-2P-DS(C)(70)		
471	755-0124-9-00	GT5EM-1P-DS		
472	757-0005-2-70	GT7-64DP-DS(70)		
473	757-0006-5-70	GT7-26DP-DS(70)		
474	757-0007-8-70	GT7-42DP-DS(70)		
475	757-0012-8-70	GT7A-64DP-DS(70)		
476	757-0013-0-70	GT7A-42DP-DS(70)		
477	758-0008-7-00	GT8Z-24DS-2C		
478	758-0009-0-00	GT8Z-14DS-2C		
479	760-0011-8-70	GT10M-6/1DP-DS(70)		
480	760-0012-0-70	GT10M-6/1DS-CV4R(70)		
481	760-0021-1-00	GT10-20/10DP-SCV		
482	760-0022-4-00	GT10-20/10DP-NSCV		
483	761-0022-0-70	GT11X-2/2P-DS(70)		
484	763-0007-0-70	GT13-1/1/1P-DS(70)		
485	763-0008-2-70	GT13-1/1/1P-DS(70)		
486	763-0042-0-70	GT13-2428/1.6-2.5SCF(70)		
487	763-0052-4-70	GT13-30/F3.3-3.8SCF(70)		
488	763-0053-7-70	GT13-30/F3.3-3.8PCF(70)		
489	763-0068-4-70	GT13-2022/F4-5SCF(70)		
490	763-0069-7-70	GT13-2428/1.6-2.5PCF(70)		

We're sorry to cause any inconvenience to you, but we have no plan to sell replacement products.

No.	Current product		Replacement product	
	Product code	Product name	Product code	Product name
491	763-0070-6-70	GT13-2022/F4-5PCF(70)		
492	763-0079-0-70	GT13-2428/F3.3-3.8PCF(70)		
493	763-0080-0-70	GT13-2428/F3.3-3.8SCF(70)		
494	763-0126-9-00	GT13L-30/1.1-2.2SCF		
495	766-0009-4-00	GT16-1P-HU		
496	779-0003-4-00	GTM5-14DS-2C		
497	781-0400-0-70	WNGT5G-0400(70)		
498	781-0401-3-70	W3GT5HFL-0401(70)		
499	781-0427-7-70	WNGT5HFC-0427(70)		
500	781-0448-7-00	WTGT5HFL-0448		
501	781-0649-9-00	W3GT5AUFL-0649		
502	781-0653-6-00	WNGT5-0653		
503	781-0662-7-00	WAEGT16-0662		
504	781-0732-0-00	WOGT5UFL-0732		
505	781-0756-9-00	WOGT16C-0756		
506	781-0769-0-00	WAEGT16CBUFL-0769		
507	781-0981-5-00	W3GT5SHFL-0981		
508	821-0003-5-40	HSC2-TM-R1(40)		
509	822-0022-6-60	LD-AP1-P1(60)		
510	822-0022-6-61	LD-AP1-P1(61)		

We're sorry to cause any inconvenience to you, but we have no plan to sell replacement products.

Acknowledgement

(Customer → Hirose Electric business representative)

Product Change Notification
Request for Your Acknowledgement

We acknowledge the aforementioned matter.

Customer's name: _____

Acknowledgement stamp (or signature): _____

HIROSE ELECTRIC CO., LTD.

(Cut on this line)

Document Receipt

(Customer → Hirose Electric business representative)

Product Change Notification
Request for Your Acknowledgement

We received the document concerning the above.

Customer's name: _____

Acknowledgment stamp (or signature): _____

HIROSE ELECTRIC CO., LTD.