



Product Change Notification - SYST-26BVVD932 (Printer Friendly)

Date:

17 Nov 2017

Product Category:

Microprocessors

Affected CPNs:**Notification subject:**

Data Sheet - SAMA5D4 Series Datasheet

Notification text:

SYST-26BVVD932

Microchip has released a new DeviceDoc for the SAMA5D4 Series Datasheet of devices. If you are using one of these devices please read the document located at [SAMA5D4 Series Datasheet](#).

Notification Status: Final

Description of Change:

Updated the following sections:

Section 3. "Package and Pinout"

- Section 3-1 "TFBGA361 Pin Description": added note (1)

Section 4. "Power Considerations"

- Table 4-1 Power Supplies: updated VDDBU minimum value from 1.88V to 1.8V

Section 12. "Standard Boot Strategies"

- Table 12-3 "PIO Driven during Boot Program Execution", SAM-BA Monitor row: corrected pin names
- Table 12-7 "Customer Fuse Matrix": added note (1)

Section 16. "Special Function Registers (SFR)"

- Removed Analog Configuration Register and modified Table 16-1 "Register Mapping" accordingly

Added Section 23. "System Controller Write Protection (SYSCWP)"

Section 32. "LCD Controller (LCDC)"

- Restored Overlay 2 Layer content.

Section 40. "Two-wire Interface (TWI)"

- Updated Table 40-7 "Register Mapping" at offset 0x44 and added Section 40.8.12 "TWI Filter Register"

Section 46. "Timer Counter (TC)"

Removed:

- Item "Read of the Capture registers by the DMAC" from the list of "Embedded Characteristics"
- Figure 45-6 "Example of Transfer with DMAC in Capture Mode"
- Section 45.7.5 "TC Register AB"

Section 56. "Electrical Characteristics"

- Table 56-54 "Two-wire Serial Bus Requirements": corrected formulas in notes (3) and (4)

Section 58. "Schematic Checklist"

- Table 58-1 "Power Supply Connections": updated VDDBU range from "1.88V to 2.12V" to "1.8V to 2.6V"

Updated Section 59. "Marking"

Section 60. "Ordering Information"

- Table 60-1 "Ordering Information": added MRL B parts
- Section 61. "Errata"

Added:

- Section 61.1 "Errata - SAMA5D4 MRL B Parts"
- Section 61.2.11 "Ethernet MAC (GMAC)"

Impacts to Data Sheet: None

Reason for Change: Conversion of Atmel datasheet to Microchip datasheet conventions.

Change Implementation Status: Complete

Date Document Changes Effective: 17 Nov 2017

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

[SAMA5D4 Series Datasheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."



[Products](#) | [Applications](#) | [Design Support](#) | [Training](#) | [Sample And Buy](#) | [About Us](#) | [Contact Us](#) | [Legal](#) | [Investors](#) | [Careers](#) | [Support](#)

©Copyright 1998-2017 Microchip Technology Inc. All rights reserved.