

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
03	070	010	0000003407	See list below	Switches	MSM with RI	-

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected



MSM19 RI							
1241.6624.1111000B	1241.6624.1112000B	3-101-884	1241.6624.1111000	1241.6624.1121000	1241.6624.1121047	1241.6624.1131000	
1241.6624.1181000	1241.6624.1112000	1241.6624.1122000	1241.6624.1122047	1241.6624.1122074	1241.6624.1132000	3-101-569	
1241.6624.1113000	1241.6624.1114000	1241.6624.1114074	1241.6624.1124000	1241.6624.1134000	1241.6624.1125000	3-100-883	
3-102-188	3-100-884	1241.6624.1114000E	1241.6624.1114074E	1241.6624.1124000E	3-103-005	1241.6924.1121000	
1241.6924.1121066	1241.6924.11220000	1241.6924.1124000	3-101-076				
MSM22 RI							
1241.6634.1111000B	1241.6634.1112000B	1241.6634.1114000B	1241.6634.1124000B	1241.6634.1115000B	1241.6934.1121000E	1241.6934.1122000E	
1241.6634.1121000	1241.6634.1131000	3-103-161	1241.6634.1112000	1241.6634.1122000	1241.6634.1132000	1241.6634.1182000	
1241.6714	3-103-170	3-103-171	3-103-627	3-103-628	1241.6634.1113000	1241.6634.1123000	
1241.6634.1114000	1241.6634.1124000	1241.6634.1134000	1241.6634.1184000	1241.6634.1125000	3-101-094	1241.6634.1111000E	
3-101-099	1241.6634.1112000E	1241.6634.1112074E	1241.6634.1114000E	1241.6634.1124000E	1241.6934.1121000	1241.6934.1122000	
3-100-882	1241.6934.1124000	1241.6934.1125000	1241.6782				
MSM30 RI							
1241.6664.3111000	1241.6664.5112000	1241.6664.1111000	1241.6664.1121000	1241.6664.1121028	1241.6664.1121029	1241.6664.1121030	
1241.6664.1121031	1241.6664.1131000	3-100-651	1241.6664.1112000	1241.6664.112000	1241.6664.1132000	3-100-652	
1241.6664.1113000	1241.6664.1123000	3-100-631	1241.6664.1114000	1241.6664.1124000	1241.6664.1134000	3-100-630	
1241.6664.1125000	1241.6664.1112000E	1241.6664.1124000E	1241.6964.1121000	1241.6964.1122000	1241.6964.1124000	1241.6731	
3-100-746	1241.7701.074	1241.7710	3-100-816	3-102-896			

2 Type of change

- The color of the illumination is slightly more intensive.

3 Detailed description of change

All MSM with ring illumination, have now an slightly more intensive color.

Old product appearance	New product appearance
	

4 Reason of change

- This change is part of the continuous improvement process.

5 Release date

The change will be rolled-out starting ww 01/2018 (Date code 1801 or higher on label) and lasts approx. 6 months depending on the variant.

6 Impact of change and recommended action

Form	No	No change in geometry
Fit	No	No change for dimension
Function	Yes	Ring illumination has slightly more intensive color
Manufacturing	No	No change for manufacturing site
Label	No	No change on label
Packaging	No	No change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
MSM19 Datasheet	
MSM22 Datasheet	
MSM30 Datasheet	

Product Change Notification					MSM RI		D10-016-742
owner	creation date	release date	released by	change order no	rev	page	
langro	05.07.2017	06.12.2017	pingelme	2014213	A	1 of 1	