

## Notification#20180717010 Datasheet for TLV3201-Q1, TLV3202-Q1 Information Only

Date: July 18, 2018 To: PREMIER FARNELL PCN

Dear Customer:

This is an information-only announcement of a change to the datasheet for a device that is currently offered by Texas Instruments.

The changes discussed within this notification are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (<u>PCN ww admin team@list.ti.com</u>).

Sincerely,

PCN Team SC Business Services

## Information Only Attachments

## **Products Affected:**

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

## DEVICE

TLV3202AQDGKRQ1

CUSTOMER PART NUMBER null

Technical details of this Product Change follow on the next page(s).

PCN Numbe		mber:	20180717010			PCN Date: July 18, 2018			18	
Title: Datasheet for TLV3201-Q1, TLV3202-Q1										
Customer Contact: PCN			PCN Manag	<u>Manager</u>			D	ept:	Quality Services	
Cha		Туре:						-		
	Assembly Site				Design			_	Wafer Bump Site	
Assembly Process					Data Sheet			=	Wafer Bump Material	
Assembly Materials					Part number change			_	Wafer Bump Process	
Mechanical Specification					Test Site Test Process			=	Wafer Fab Site Wafer Fab Materials	
Packing/Shipping/Labeli			abeing		Test Proce	55	╞		r Fab Process	
				N						
Description of Change:										
Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.										
TEXAS INSTRUMENTS TLV3201-Q1, TLV3202-Q1 SBOS856A – FEBRUARY 2017 – REVISED DECEMBER 2017										
Changes from Original (February 2017) to Revision A Page										
•	Changed figure 29									
The datasheet number will be changing.										
	Device Family			9		Change From:		Change To:		
TLV3201-Q1, TLV3202-Q1			2-Q1		SBC	80S584D		SBOS	SBOS584E	
These changes may be reviewed at the datasheet links provided.										
http://www.ti.com/product/TLV3201-Q1										
Reason for Change:										
To accurately reflect device characteristics.										
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):										
No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.										
Changes to product identification resulting from this PCN:										
None.										
Product Affected:										
TLV3201AQDCKRQ1 TLV3202AQDGKRQ										
For	For questions regarding this notice, e-mails can be sent to the regional contacts shown below								acts shown below	

or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com