

## Product Change Notice

PCN#: EE-PCN18031

8/1/2018

**CLASSIFICATION OF CHANGE:**

End of Life (EOL)

**DESCRIPTION OF CHANGE:**

Various fuses have reached EOL

**REASON FOR CHANGE:**

In pursuit of Eaton's sustainability goals and RoHS compliance commitment, non-RoHS compliant fuses have reached end of life status.

**EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:**

There are no differences in the quality, reliability, or performance between RoHS compliant and non-RoHS compliant products or any changes to form, fit, and function of these fuses.

**PARTS FAMILIES AFFECTED:**

Fuses in C180 and TDC600 families are affected. Please see attached for detailed part numbers. Any inventory of existing product is saleable and should not be returned.

**TIME SCHEDULE:**

Effective immediately

**ISSUED BY:**

Wayne Wang  
Product Manager – Circuit Protection

**CONTACT INFORMATION:**

For questions or comments, please contact your local [Eaton sales representative](#).

Fuse Family	None-RoHS Compliant Part Number	RoHS Compliant Replacement
C180	BK-TDC180-1	BK-TDC180-1A
C180	BK-TDC180-10	BK-TDC180-10A
C180	BK-TDC180-13	BK-TDC180-13A
C180	BK-TDC180-2	BK-TDC180-2A
C180	BK-TDC180-3	BK-TDC180-3A
C180	BK-TDC180-5	BK-TDC180-5A
C180	BK-TDC180-7	BK-TDC180-7A
TDC600	BK-TDC600-10A	BK-TDC600-10-R
TDC600	BK-TDC600-2A	BK-TDC600-2-R
TDC600	BK1-TDC600-10A	BK1-TDC600-10-R
TDC600	TDC600-10A	TDC600-10-R
TDC600	TDC600-2A	TDC600-2-R