

# Change Notice

# S & SW Series

## Changes to Identification for S821 & SW3821

Type of Change:

- Engineering     Part Number  
 Product         Appearance

There will be revisions to the identification label on S821 Toggles and SW3821 Rockers. The label had displayed the letters "MLP" under the part number, which will be replaced with NKK's updated logo. These changes will apply to standard and custom part numbers, and the differences for both of the switches are shown below.



Changes for S821 & SW3821

Part Numbers	Identification Label	
	Before Change	After Change
S821 S821/328 S821/CUL S821/C-UL S821/U S821/UC	<b>MLP</b> displayed under part no. on right side of identification label	<b>NKK Logo</b> displayed under part no. on right side of identification label
SW3821 SW3821/A/UC SW3821/CUL SW3821/U SW3821/UC	<b>MLP</b> displayed under part no. on right side of identification label	<b>NKK Logo</b> displayed under part no. on right side of identification label

### Notes

There are no changes to the switches' dimensions or specifications.  
 Contact the factory if more details are needed.

### Effective Date

Identification changes for S821 Toggles and SW3821 Rockers will be effective September 2018.

**NKK**  
SWITCHES

www.nkkswitches.com • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435