



12500 TI Boulevard, MS 8640, Dallas, Texas 75243

PDN# 20181002000.3
Discontinuance of Select TLCxxxx devices
Product Discontinuance Notification

Date: October 03, 2018
To: Newark/Farnell PCN

Dear Customer:

The recipient has been identified for notification of changes for one or more of the products affected by the change detailed in the notice. Customers are notified based on the past twenty-four (24) months of the customer's purchase history or the recipient is listed as being part of GIDEP (Government-Industry Data Exchange Program).

TI would appreciate it if you would notify us of any future demand and estimated quantities needed for the affected products as soon as possible.

In an attempt to satisfy continuing requirements, TI is offering a non-cancelable, non-refundable lifetime buy for the product. Related dates are included in the notification. We will contact you as soon as we have completed a review of all customer responses and determined the appropriate course of action required to satisfy the need for this/these products.

The notification period is governed by TI's standard process. Any inquiries should be directed to your local Field Sales Representative.

If you require additional supply beyond the dates defined in this letter, please contact your local Field Sales Representative to determine if the parts may be available from a TI-authorized distributor for discontinued products. There is no guarantee of continued supply for these products.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (PCN_ww_admin_team@list.ti.com).

Sincerely,

PCN Team
SC Business Services

**20181002000.3
Attachments1**

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, you have purchased this device within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE	CUSTOMER PART NUMBER
TLC548CP	null
TLC549CP	null
TLC1541IN	null
TLC541IN	null
TLC549CD	null
TLC549ID	null
TLC549IP	null
TLC542IN	null

Details of this Product Discontinuance follow on the next page(s).

PDN Number:	20181002000.3		PDN Date:	Oct 3, 2018
Title:	Discontinuance of Select TLCxxxx devices			
Customer Contact:	PCN Manager		Dept:	Quality Services
Last date to order:	Oct 3, 2019	Last date to ship:	Apr 3, 2020	
Change Type:	Product Discontinuance - End Of Life			
Product Discontinuance Notification Details				
Description of Discontinuance:				
Texas Instruments, Incorporated (TI) is announcing the discontinuance of select TLCxxx devices. A life time buy is being offered per the date shown above. Recommended replacements are being offered as shown in the Product Affected Section.				
NOTE: There are no samples offered for withdrawn/obsolete products. For samples of any replacement products, please contact your local sales representative.				
Reason for Withdrawal/Discontinuance:				
Potential continued reliable product support is at risk due to an unsupported tool set which could not be offloaded.				
Product Affected:				
DEVICES BEING DISCONTINUED	RECOMMENDED REPLACEMENT PRODUCTS		REPLACEMENT CODES	
TLC1541CDW	ADS7956SDBT		F	
TLC1541CFN	ADS7956SRHBT		F	
TLC1541CN	ADS7956SDBT		F	
TLC1541IDW	ADS7956SDBT		F	
TLC1541IDWR	ADS7956SDBTR		F	
TLC1541IFN	ADS7956SRHBT		F	
TLC1541IFNG3	ADS7956SRHBT		F	
TLC1541IN	ADS7956SDBT		F	
TLC540IDW	ADS7960SDBT		F	
TLC540IDWR	ADS7960SDBTR		F	
TLC540IFN	ADS7960SRHBT		F	
TLC540IFNG3	ADS7960SRHBT		F	
TLC540IFNR	ADS7960SRHBR		F	
TLC540IN	ADS7960SDBT		F	
TLC541IDW	ADS7960SDBT		F	
TLC541IDWR	ADS7960SDBTR		F	
TLC541IFN	ADS7960SRHBT		F	
TLC541IFNR	ADS7960SRHBR		F	
TLC541IN	ADS7960SDBT		F	
TLC542CDW	ADS7960SDBT		F	
TLC542CDWG4	ADS7960SDBT		F	
TLC542CDWR	ADS7960SDBTR		F	
TLC542CN	ADS7960SDBT		F	
TLC542CNE4	ADS7960SDBT		F	

TLC542IDW	ADS7960SDBT	F
TLC542IDWG4	ADS7960SDBT	F
TLC542IDWR	ADS7960SDBTR	F
TLC542IFN	ADS7960SRHBT	F
TLC542IFNR	ADS7960SRHBR	F
TLC542IFNRG3	ADS7960SRHBR	F
TLC542IN	ADS7960SDBT	F
TLC545CFN	ADS7961SRHBT	F
TLC545IFN	ADS7961SRHBT	F
TLC548CD	ADC081S021CIMF/NOPB	F
TLC548CDR	ADC081S021CIMFX/NOPB	F
TLC548CP	ADC081S021CIMF/NOPB	F
TLC548ID	ADC081S021CIMF/NOPB	F
TLC548IDR	ADC081S021CIMFX/NOPB	F
TLC548IP	ADC081S021CIMF/NOPB	F
TLC549CD	ADC081S021CIMF/NOPB	F
TLC549CDG4	ADC081S021CIMF/NOPB	F
TLC549CDR	ADC081S021CIMFX/NOPB	F
TLC549CDRG4	ADC081S021CIMFX/NOPB	F
TLC549CP	ADC081S021CIMF/NOPB	F
TLC549ID	ADC081S021CIMF/NOPB	F
TLC549IDG4	ADC081S021CIMF/NOPB	F
TLC549IDR	ADC081S021CIMFX/NOPB	F
TLC549IDRG4	ADC081S021CIMFX/NOPB	F
TLC549IP	ADC081S021CIMF/NOPB	F
TLC549IPS	ADC081S021CIMF/NOPB	F
TLC549IPSR	ADC081S021CIMFX/NOPB	F

Replacement Notes:

F = Similar functionality but not equivalent.

P = Same functionality but not pin-for-pin equivalent and may not be parametrically equivalent.

Q = Same functionality and PIN-OUT as the compared device but is NOT an exact equivalent.

S = EXACT equivalent in functionality and parametrically to the compared device.

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com